

PRODUCT CHANGE NOTIFICATION

Product Category OUTLETS 20200807-1

Product Group ROAR

ISSUE DATE: **NA** **EMEA** **LATAM** **AP** Aug-20


IMPACTED REGIONS: **DISCONTINUATION**

REASON FOR CHANGE: **OTHER**


DESCRIPTION OF CHANGE: (Required)

Angled versions of patch panel brackets (2RU, 3RU and 4RU) will be discontinued. 2RU brackets will no longer be available. Straight 3RU and 4RU sized brackets will remain available for purchase.

Angled version of patch panel brackets



Straight version of patch panel brackets



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2020	11	10

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-Customer-Service@panduit.com	CHINA: 800-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) IND-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-3776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
NORTH AMERICA USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA		EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

IMPACTED PART NUMBER(S)	Replacement Type	Replacement Part 1	Replacement Part 2
CPPBRKT/N	No Replacement		
CPPBRKT3/N	Direct Replacement	CPPTBRKT3/N	
CPPBRKT4/N	Direct Replacement	CPPTBRKT4/N	