



Product Change Notification

Current Date: 17-Sep-2020

TE Connectivity

Product Change Notification: E-20-012664

PCN Date: 17-SEP-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
P1 Relay family removing "Resistance to soldering profile"

Description of Changes
P1 Relay family datasheet update: remove graph for "Resistance to soldering heat profile"

Reason for Changes:
Manufacturing / Process Requirements. Document clarification

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	18-SEP-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393774-0	NO		TYC1-1393774-0	V23026A1003B201			
1-1393774-2	NO		TYC1-1393774-2	V23026A1004B201			
1393774-1	NO		TYC1393774-1	V23026A1001B201			
1393774-8	NO		TYC1393774-8	V23026A1002B201			
1393775-2	NO		TYC1393775-2	V23026B1105B201			
1393776-3	NO		TYC1393776-3	V23026D1021B201*X020, V23026D1021B201 *X020			
1393776-7	NO		TYC1393776-7	V23026D1024B201*X020, V23026D1024B201 *X020			
1393776-8	NO			V23026D1026B201*X020, V23026D1026B201 *X020			
1422015-6	NO		TYC1422015-6				
1422015-8	NO		TYC1422015-8				
3-1393774-4	NO		TYC3-1393774-4	V23026B1101B201			
3-1393774-5	NO		TYC3-1393774-5	V23026B1102B201			



Product Change Notification

Current Date: 17-Sep-2020

TE Connectivity

Product Change Notification: E-20-012664

PCN Date: 17-SEP-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
P1 Relay family removing "Resistance to soldering profile"

Description of Changes
P1 Relay family datasheet update: remove graph for "Resistance to soldering heat profile"

Reason for Changes:	
Manufacturing / Process Requirements. Document clarification	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	18-SEP-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393774-0	NO		TYC1-1393774-0	V23026A1003B201			
1-1393774-2	NO		TYC1-1393774-2	V23026A1004B201			
1393774-1	NO		TYC1393774-1	V23026A1001B201			
1393774-8	NO		TYC1393774-8	V23026A1002B201			
1393776-3	NO		TYC1393776-3	V23026D1021B201*X020, V23026D1021B201 *X020			
1393776-7	NO		TYC1393776-7	V23026D1024B201*X020, V23026D1024B201 *X020			
1393776-8	NO			V23026D1026B201*X020, V23026D1026B201 *X020			
3-1393774-4	NO		TYC3-1393774-4	V23026B1101B201			
3-1393774-5	NO		TYC3-1393774-5	V23026B1102B201			