



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019870

PCN Date: 20-OCT-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Manufacturing location change product change notification

Description of Changes
The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:
Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
106021-000	NO		RAY106021-000	5-1190774-7, TXR54AB00-1408AI			
111209-000	NO			9-1190811-9, TXR40BW00-2218AI			
121571-000	NO		RAY121571-000, RAYTXR40AB00-1610AI	9-1190884-5, TXR40AB00-1610AI			
132041-000	NO			8-1190959-1, TXR40SJ00-1408AI			
132377-000	NO			1190962-7, STXR40AB00-1816AI			
243827-000	NO			9-1191788-3, TXR40AB00-2406AI			
255423-000	NO			8-1191869-4, TXR41AB00-0805AI			
327541-000	NO			1192478-8, TXR40BW00-1410AI			
329041-000	NO			9-1192487-1, TXR41AB00-2418AI			
332333-000	NO			1192511-4, TXR40AC00-1814AI			
353505-000	NO			1192655-2, TXR21AB00-2412AI			
357409-000	NO			8-1192681-4, TXR40SJ00-2010AI			
365799-000	NO		RAY365799-000	9-1192742-5, TXR40AB00-2420AI			
372355-000	NO			9-1192788-9, TXR58AB00-1606AI			
396063-000	NO		RAY396063-000	9-1192970-5, TXR40AB00-2410AI			
411287-000	NO			9-1193101-2, TXR21AB00-2012AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
416179-000	NO			7-1193136-4, STXR40AB90-1412AI			
469059-000	NO		RAY469059-000	4-1193515-6, TXR40AB00-2414BI			
470290-000	NO			3-1193524-1, TXR41AB00-1206AI			
489463-000	NO			1193662-4, TXR40AB00-2008BI			
530905-000	NO			7-1194169-0, TXR54AB00-2210AI			
557477-000	NO			2-1194397-4, TXR40AB00-1616AI			
589103-000	NO			4-1194661-9, TXR54AB45-1812AI			
639347-000	NO			3-1195053-6, TXR54AB00-1608AI			
676087-000	NO			5-1195316-2, TXR40BW00-2010AI			
693843-000	NO			4-1195444-6, STXR40SJ00-1614AI			
742053-000	NO		RAY742053-000	8-1195790-7, TXR40BW00-1205AI			
766745-000	NO			8-1195975-3, TXR40BW00-1612AI			
792247-000	NO			2-1196135-7, TXR41AB90-0804BI			
794653-000	NO			8-1196151-1, TXR41AB90-1410BI			
808825-000	NO			8-1196281-4, 201M920-19G			
860537-000	NO			7-1196704-1, 204M012-19B04-40			
875353-000	NO			4-1196809-3, TXR40BW00-1610BI			
888679-000	NO			5-1196913-0, STXR41AB00-2218AI			
900071-000	NO			5-1196996-1, 209M308-19B			
934921-000	NO			2-1197244-3, TXR54AB00-3220AI			
971171-000	NO		RAY971171-000	2-1197507-2, TXR40AB00-1405AI			
A91347-000	NO			5-1200726-3, TXR40AU00-1007AI			
AAD9804-00	NO			EM3292-000,, TXR40AZ90-1816AI			
CW0601-000	NO			TX54AZ00-1406			
E73623-000	NO			1-1201225-8, TXR40SJ90-1407AI			
EF9299-000	NO			TX54AZ00-2206			
EG1537-000	NO			BND40AB00-1006W			
EJ3154-000	NO			STXR40BW00-1616AI			
EK2355-000	NO			225M328-19U			
EM7866-000	NO			TXR40AB90-1805BI			



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019870

PCN Date: 20-OCT-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Manufacturing location change product change notification

Description of Changes
The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:
Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
106021-000	NO		RAY106021-000	5-1190774-7, TXR54AB00-1408AI			
111209-000	NO			9-1190811-9, TXR40BW00-2218AI			
121571-000	NO		RAY121571-000, RAYTXR40AB00-1610AI	9-1190884-5, TXR40AB00-1610AI			
132041-000	NO			8-1190959-1, TXR40SJ00-1408AI			
132377-000	NO			1190962-7, STXR40AB00-1816AI			
243827-000	NO			9-1191788-3, TXR40AB00-2406AI			
255423-000	NO			8-1191869-4, TXR41AB00-0805AI			
327541-000	NO			1192478-8, TXR40BW00-1410AI			
329041-000	NO			9-1192487-1, TXR41AB00-2418AI			
332333-000	NO			1192511-4, TXR40AC00-1814AI			
353505-000	NO			1192655-2, TXR21AB00-2412AI			
357409-000	NO			8-1192681-4, TXR40SJ00-2010AI			
365799-000	NO		RAY365799-000	9-1192742-5, TXR40AB00-2420AI			
372355-000	NO			9-1192788-9, TXR58AB00-1606AI			
396063-000	NO		RAY396063-000	9-1192970-5, TXR40AB00-2410AI			
411287-000	NO			9-1193101-2, TXR21AB00-2012AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
416179-000	NO			7-1193136-4, STXR40AB90-1412AI			
470290-000	NO			3-1193524-1, TXR41AB00-1206AI			
489463-000	NO			1193662-4, TXR40AB00-2008BI			
530905-000	NO			7-1194169-0, TXR54AB00-2210AI			
557477-000	NO			2-1194397-4, TXR40AB00-1616AI			
589103-000	NO			4-1194661-9, TXR54AB45-1812AI			
639347-000	NO			3-1195053-6, TXR54AB00-1608AI			
676087-000	NO			5-1195316-2, TXR40BW00-2010AI			
693843-000	NO			4-1195444-6, STXR40SJ00-1614AI			
742053-000	NO		RAY742053-000	8-1195790-7, TXR40BW00-1205AI			
766745-000	NO			8-1195975-3, TXR40BW00-1612AI			
792247-000	NO			2-1196135-7, TXR41AB90-0804BI			
794653-000	NO			8-1196151-1, TXR41AB90-1410BI			
808825-000	NO			8-1196281-4, 201M920-19G			
860537-000	NO			7-1196704-1, 204M012-19B04-40			
875353-000	NO			4-1196809-3, TXR40BW00-1610BI			
888679-000	NO			5-1196913-0, STXR41AB00-2218AI			
900071-000	NO			5-1196996-1, 209M308-19B			
934921-000	NO			2-1197244-3, TXR54AB00-3220AI			
971171-000	NO		RAY971171-000	2-1197507-2, TXR40AB00-1405AI			
A91347-000	NO			5-1200726-3, TXR40AU00-1007AI			
AAD9804-00	NO			EM3292-000,, TXR40AZ90-1816AI			
CW0601-000	NO			TX54AZ00-1406			
E73623-000	NO			1-1201225-8, TXR40SJ90-1407AI			
EF9299-000	NO			TX54AZ00-2206			
EG1537-000	NO			BND40AB00-1006W			
EJ3154-000	NO			STXR40BW00-1616AI			
EK2355-000	NO			225M328-19U			
EM7866-000	NO			TXR40AB90-1805BI			