



Product Change Notification

Current Date: 06-Dec-2020

TE Connectivity

Product Change Notification: P-20-020159

PCN Date: 04-DEC-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Hollow Shaft Resolvers, V23401 Family

Description of Changes

This product change notification is related to all TE size 21 resolvers that have NiFe material as part of the stator and rotor transformer. In order to ensure component availability, there will be a second source of equivalent NiFe raw material implemented in addition to the existing material. There is no change in resolver manufacturing process, product form, fit and any technical functions. Please don't hesitate to contact your TE representative in case of any questions.

Other attachments:

[TE Resolvers Size 21_Siemens](#)

Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

15-FEB-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1393048-2	NO		TYC4-1393048-2	"V23401T2009B202"			
4-1393048-6	NO		TYC4-1393048-6	"V23401T2014B209"			



Product Change Notification

Current Date: 06-Dec-2020

TE Connectivity

Product Change Notification: P-20-020159

PCN Date: 04-DEC-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Hollow Shaft Resolvers, V23401 Family

Description of Changes

This product change notification is related to all TE size 21 resolvers that have NiFe material as part of the stator and rotor transformer. In order to ensure component availability, there will be a second source of equivalent NiFe raw material implemented in addition to the existing material. There is no change in resolver manufacturing process, product form, fit and any technical functions. Please don't hesitate to contact your TE representative in case of any questions.

Other attachments:

[TE Resolvers Size 21_Siemens](#)

Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

15-FEB-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1393048-2	NO		TYC4-1393048-2	"V23401T2009B202"			
4-1393048-6	NO		TYC4-1393048-6	"V23401T2014B209"			

Nr.	TE Part Numbers	Resolvers Descriptions
#	TCPN	TE Part Description
1	1-1414028-0	RESOLVER V23401-T2109-E102
2	1-1414203-0	RESOLVER V23401-T2015-B201
3	1-1414277-0	RESOLVER V23401-T2650-D209
4	1-1414278-0	RESOLVER V23401-T2654-D209
5	1-1414281-0	RESOLVER V23401-T2532-C209
6	1-1414282-0	RESOLVER V23401-T2652-C309
7	1-1414284-0	RESOLVER V23401-T2639-C202
8	1-1414612-0	RESOLVER V23401-T2014-E209
9	1-1414613-0	RESOLVER V23401-T2009-E202
10	1-1414614-0	RESOLVER V23401-T2002-E209
11	1-1414618-0	RESOLVER V23401-T2099-C502
12	1-1824526-0	RESOLVER V23401-T2014-D309
13	1-1824527-0	RESOLVER V23401-T2009-D302
14	1-1824528-0	RESOLVER V23401-T2002-D309
15	1-1824529-0	RESOLVER V23401-T2J14-E209
16	1-1824530-0	RESOLVER V23401-T2J09-E202
17	1-1824531-0	RESOLVER V23401-T2J02-E209
18	1-1824532-0	RESOLVER V23401-T2J10-E209
19	1-1824533-0	RESOLVER V23401-T2J14-D309
20	1-1824534-0	RESOLVER V23401-T2J14-B209
21	1-2246390-0	RESOLVER V23401-T2L14-E209
22	1-2246391-0	RESOLVER V23401-T2L09-E202
23	2297137-1	RESOLVER V23401-T2L09-D302
24	2297138-1	RESOLVER V23401-T2L02-D309
25	2297202-1	RESOLVER V23401-T2M14-D309
26	2297203-1	RESOLVER V23401-T2M09-D302
27	2297204-1	RESOLVER V23401-T2M02-D309
28	2320385-1	RESOLVER V23401-T2P09-D302
29	2340309-1	RESOLVER V23401-T2002-D309 LOW TR
30	2340310-1	RESOLVER V23401-T2014-D309 LOW TR
31	2372428-1	RESOLVER V23401-T2J15-E201
32	2376235-1	RESOLVER V23401-T2P09-G102
33	3-1414773-4	RESOLVER V23401-T2015-E201
34	4-1393048-0	RESOLVER V23401-T2001-B202
35	4-1393048-1	RESOLVER V23401-T2002-B209
36	4-1393048-2	RESOLVER V23401-T2009-B202
37	4-1393048-6	RESOLVER V23401-T2014-B209
38	4-1393048-7	RESOLVER V23401-T2109-C302
39	1-2246455-1	RESOLVER V23401-T2L34-E209
40	2289921-1	RESOLVER V23401-T2034-D309
41	2289924-1	RESOLVER V23401-T2L34-D309

TE HOLLOW SHAFT RESOLVERS SIZE 21

42	2302148-1	RESOLVER V23401-T2J34-D309
43	2336161-1	RESOLVER V23401-T2034-D309 CHINA PH 1
44	2362847-1	RESOLVER V23401-T2J44-D309