

<b>NO:</b> PMS - 026	<b>PRODUCT:</b> B5W-LD0101-1 & B5W-LD0101-2 – Air Quality Sensors
<b>DATE:</b> February 2021	<b>TYPE:</b> DISCONTINUATION – Streamline Product offering

## B5W-LD0101-1 & B5W-LD0101-2 Air Quality Sensors - DISCONTINUATION

In an effort to streamline our product offering, OMRON will discontinue the B5W-LD0101-1 & B5W-LD0101-2 Air Quality sensors in February 2022. There is no suggested replacement for these sensors. The following notification will explain the discontinuation; should you have any additional questions, however, please communicate with the Sensor Product Manager, Cary Horan.



### LAST Order date (Last Time Buy Date)

February 28, 2022

Product Discontinuation		Suggested Replacement
Including, but not limited to, the following:		
Air Quality Sensor		
Model B5W-LD0101-1	➔	No Suggested Replacement
Model B5W-LD0101-2		

\* Sales teams should communicate this discontinuation with their OEM's and CEM's.  
For further technical support and any questions, please communicate with Product Marketing.

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.  
This PCN is intended for use in the Americas  
Last time buy dates are subject to change based on availability