

Product discontinuation notification (PDN)

Title / short description	Discontinuation of the PLH 16 series
Affected article category	PCB terminal blocks and PCB connectors
Change category	Discontinuation
Change number	IAA200009-00

Purpose/objective of the change

Discontinuation of the PLH 16 series

Detailed description of the change

We aim to provide you with state-of-the-art products for your application. It is therefore necessary to phase out some components from time to time for commercial or technical reasons.

This correspondence is therefore notice of the discontinuation of the PLH 16 series terminal blocks. Alternative items are available in the LPT 16 series. The technical performance data of these items is the same or better. The size and pin layout are different. Details of these differences are available in the comparison drawings in the attachment. We will be happy to implement your desired variant, such as a printed item, on request.

The following schedule applies: Final order: January 31, 2022 // Final delivery: July 31, 2022.

Thank you for your understanding, and we look forward to continuing our successful cooperation.

Identifying characteristics

Discontinuation

Start of Production (SOP)	-	Last Time Delivery (LTD)	2022-07-31
Effective date (EOP)	2022-02-01	End of Service (EOSR)	-
End of Sales (EOS)	2022-01-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Comparison drawing PLH 16-10_LPT 16-10.pdf
- Comparison drawing PLH 16-15_LPT 16-15.pdf
- Material_list.csv
- PDN-IAA200009-00 Abkündigung der PLH 16 Serie_DE
- PDN-IAA200009-00 Discontinuation of the PLH 16 series_EN

Material list

Item	Article Type	Hardware old	Firmware new	Item	Substitute item Type
1703995	PLH 16/ 1-10	2	2	1119809	LPT 16/ 1-10,0
1045845	PLH 16/ 4-15 MC BD:-L3MQ	1	1		
1048853	PLH 16/ 3-10 GY7035 BD:R-S	0	0		
1257085	PLH 16/ 2-10 BD:RB,RB	0	0		
1703268	PLH 16/ 2-15 MIX BK/RD	2	2		
1704568	PLH 16/ 1-10 GY	1	1		
1708845	PLH 16/ 5-10 BU/GY/GY/GY/GN	0	0		
1709774	PLH 16/ 2-10 BD:+,-	0	0		
1712963	PLH 16/ 3-15 BD:5L3-1L1SO	0	0		
1712964	PLH 16/ 3-15 BD:2T1-6T3	0	0		
1770393	PLH 16/ 2-10	3	3		
1770403	PLH 16/ 3-10	3	3		
1770416	PLH 16/ 4-10	3	3		
1770429	PLH 16/ 5-10	3	3		
1770432	PLH 16/ 6-10	3	3		
1770445	PLH 16/ 7-10	3	3		
1770458	PLH 16/ 8-10	3	3		
1770461	PLH 16/ 2-10-ZF	3	3	1119810	LPT 16/ 2-10,0-ZB
1770474	PLH 16/ 3-10-ZF	3	3	1119811	LPT 16/ 3-10,0-ZB
1770487	PLH 16/ 4-10-ZF	3	3	1119812	LPT 16/ 4-10,0-ZB
1770490	PLH 16/ 5-10-ZF	3	3	1119814	LPT 16/ 5-10,0-ZB
1770500	PLH 16/ 6-10-ZF	3	3	1119815	LPT 16/ 6-10,0-ZB
1770513	PLH 16/ 7-10-ZF	3	3	1119816	LPT 16/ 7-10,0-ZB
1770526	PLH 16/ 8-10-ZF	3	3	1119817	LPT 16/ 8-10,0-ZB
1770539	PLH 16/ 2-15	3	3	1119818	LPT 16/ 2-15,0-ZB
1770542	PLH 16/ 3-15	3	3	1119819	LPT 16/ 3-15,0-ZB
1770555	PLH 16/ 4-15	3	3	1119820	LPT 16/ 4-15,0-ZB
1770568	PLH 16/ 5-15	3	3	1119821	LPT 16/ 5-15,0-ZB
1770571	PLH 16/ 6-15	3	3		
1770584	PLH 16/ 7-15	3	3		
1770597	PLH 16/ 8-15	3	3		
1797402	PLH 16/ 3-10-ZF BD:L-PE	3	3		
1804178	PLH 16/ 5-10 BD:L1-PE	2	2		
1819707	PLH 16/ 3-10-ZF MC-GY,BU,GN,YE	1	1		
1825115	PLH 16/ 6-15 MIX BK/GN/BK	1	1		
1825128	PLH 16/ 3-15 MIX GN/BK	1	1		
1828853	PLH 16/ 2-10-ZB BK	1	1		
1845687	PLH 16/ 2-15 BK	0	0		

Item	Article Type	Hardware / Firmware old	new	Item	Substitute item Type
1037226	PLH 16/ 2-15 BD:-3L2SO	0	0		