



26-Mar-2021

PCN #:E-21-001572

Subject:No action is required at this time. Parts and drawings have been clarified and corrected.

Description of Change: Parts and tools in the field are not affected. The following drawings have been modified for clarification. 2305567, 2326267, 2326270, 2350391,679231.

Reason: Document Clarification.

Key Dates:

Contact By Date:30-Apr-2021

Implementation Date:30-Apr-2021

| Product Affected | Alias Part Number |
|-------------------------|--------------------------|
|-------------------------|--------------------------|

| | |
|----------|--|
| 679231-1 | |
|----------|--|

| | |
|-----------|--|
| 2305567-1 | |
|-----------|--|

| | |
|-----------|--|
| 2350391-1 | |
|-----------|--|

| | |
|-----------|--|
| 2326270-1 | |
|-----------|--|

| | |
|----------|--|
| 679231-5 | |
|----------|--|

| | |
|-----------|--|
| 2326267-1 | |
|-----------|--|

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.