

Product Advisory

PCN#: V21-009-F-MA0
Issue Date: April 26, 2021

Change Type:

Update Broadcom LPN Label Format.



Parts Affected:

Optical transceivers/AOCs from Optical Systems Division

Product Family	Broadcom Part Numbers
MTRJ	HFBR-5912xxx
1x9 Multi-mode	HFBR-53A5xxx
1x9 Single-mode	AFCT-5805xxx AFCT-5815xxx AFCT-517xxx AFCT-5971xxx
Single mode OC3/OC12	AFCT-576xxx AFCT-575xxx AFCT-596xxx
1G LX	AFCT-570xxx AFCT-571xxx
1G SX SFP	AFBR-570x-xxx AFBR-571x-xxx AFBR-57L5xxx
1G SX SFF	HFBR-5911xxx
1G CuSFP	ABCU-57xxxx
Fibre Channel 4G	AFBR-592xx AFBR-59x5x AFBR-59R6x
Fibre Channel 8G	AFCT-57D3xxx AFBR-57D9xxx
Fibre Channel 16G	AFBR-57F5xxx AFCT-57F3xxx
Fibre Channel 32G	AFBR-57G5xxx AFCT-57G5xxx
Fibre Channel 64G	AFBR-57H5xxx
10G SFP+ SR/LR	AFBR-709xxx AFBR-710xxx AFCT-739xxx
25G SFP28 SR/LR	AFBR-725xxx AFBR-73xxxx AFCT-725xxx
25G AOC	AFBR-8CERxxZ-xxx

Product Family	Broadcom Part Numbers
CFP2 SR10 MM	AFBR-842xxx
CXP2 AOC	AFBR-86EDxxZ-xxx AFBR-86YDxxZ-xxx
CXP Transceiver	AFBR-83xxx
MiniPod	AFBR-82xxx AFBR-81xxx
MicroPod	AFBR-77Dxxx AFBR-78Dxxx
40G QSFP+ BiDi	AFBR-79EBxxx
40G QSFP+ iSR4	AFBR-79EIxxx
40G QSFP+ SR4	AFBR-79EAxZ AFBR-79EQxZ
40G QSFP+ eSR4	AFBR-79EExxx
100G QSFP28 BiDi	AFBR-89BDDZ-xxx
100G QSFP28 SR4	AFBR-89CxDZ-xxx AFBR-89CxHZ-xxx
100G QSFP28 DR1	AFCT-89SDDZ-xxx
100G QSFP28 FR1	AFCT-89SFDZ-xxx
400G QSFP-DD DR4	AFCT-91DRxxZ-xxx

Description and Extent of Change:

Item	Plan of Record (Existing)	Proposed Change
1	LPN Label – Human Readable Made In: China / Malaysia / Philippines / Vietnam	LPN Label – Human Readable (4L) Made In: China / Malaysia / Philippines / Vietnam
2	LPN Label - Made In 1D Barcode Content: China / Malaysia / Philippines / Vietnam	LPN Label - Made In 1D Barcode Content: 4LCN / 4LMY / 4LPH / 4LVN
3	LPN Label - Made In 2D Barcode Content: 1T+LPN,1L+LPN,Q+QTY,8D+MFG Date,9D+Date Code,4L+COO  1TFGL14A0001,1LFGL14A0001,Q60,8D29-MAR-2021,9D2114,4LCHINA	LPN Label - Made In 2D Barcode Content: 1T+LPN,1L+LPN,Q+QTY,8D+MFG Date,9D+Date Code,4L+ 2-digits COO  1TFGL14A0001,1LFGL14A0001,Q60,8D29-MAR-2021,9D2114,4LCN

Item	Plan of Record (Existing)	Proposed Change
4	LPN Label with FIT Logo  LS0035 RoHS Compliant	LPN Label with AVAGO Logo  LS0035 RoHS Compliant

Reasons for Change:

To comply with ISO/IEC 15418 standard.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No changes to fit, form, function, quality or reliability to the transceiver/AOC products

Effective Date of Change:

Product shipments with new LPN format will begin 90 days from this notice, starting July 25, 2021.

Recommended Actions to be taken by Customer:

No action required.

These changes have been reviewed and approved by Broadcom engineers and managers per Broadcom's procedure. Please contact your Broadcom Field Sales Engineer or Contact Center (<https://www.broadcom.com/company/contact/>) for any questions or support requirements.