



Product Change Notification

Current Date: 05-May-2021

TE Connectivity

Product Change Notification: E-21-004947

PCN Date: 05-MAY-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
CPC Connectors

Description of Changes
Delete the existing AMP logo molded into the housing. Add a molded TE logo close to the molded part number where possible. The molded TE logo and molded part number may be located on any flange edge of receptacles or body of plugs.

Reason for Changes:
Product Improvement. Change brand marking from AMP to TE. TE considers this a form change because the logos are external visible features of the parts.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	10-NOV-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-NOV-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-796433-1	NO						
206037-1	NO		TYC206037-1	"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO		TYC206037-2				
206044-1	NO		TYC206044-1				
206137-1	NO		TYC206137-1				
206137-2	NO		TYC206137-2				
206137-5	NO						
206151-1	NO		TYC206151-1				
206151-2	NO		TYC206151-2				
206151-3	NO		TYC206151-3, TYC8-1532247-0				
206306-1	NO		TYC206306-1				
206306-2	NO		TYC206306-2				
206425-1	NO		TYC206425-1	"4-40001-7431"			
206425-2	NO		TYC206425-2				
206430-1	NO		TYC206430-1				
206430-2	NO		TYC206430-2	"5011473", "CL0834-000", "JOR-06588"			
206613-1	NO		TYC206613-1				
206705-1	NO		TYC206705-1	"683370-000", "AMPS-0-0206705-1"			
206705-2	NO		TYC206705-2	"195902-000", "AMPS-0-0206705-2"			
206705-3	NO		TYC206705-3				
206705-4	NO		TYC206705-4				
207486-1	NO		TYC207486-1	"402697510"			
207486-5	NO		TYC207486-5				
211401-1	NO		TYC211401-1				
211401-2	NO		TYC211401-2				
211401-3	NO		TYC211401-3				
211401-4	NO						
211769-1	NO		TYC211769-1				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
211769-3	NO		TYC211769-3				
788155-2	NO		TYC788155-2				
788159-2	NO		TYC788159-2				
796271-1	NO		TYC796271-1				
796274-1	NO		TYC796274-1				

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
206037	206037-1	TYC206037-1	L	
206044	206044-1	TYC206044-1	G1	
206137	206137-1	TYC206137-1	M1	
206151	206151-1	TYC206151-1	P	
206306	206306-1	TYC206306-1	M	
206425	206425-1	TYC206425-1	J1	
206430	206430-1	TYC206430-1	K	
206613	206613-1	TYC206613-1	T	
206705	206705-1	TYC206705-1	P	
207486	207486-1	TYC207486-1	T1	
211401	211401-1	TYC211401-1	K	
211769	211769-1	TYC211769-1	H	
788159	788159-2	TYC788159-2	C	
796271	796271-1	TYC796271-1	D	
796274	796274-1	TYC796274-1	F	



Product Change Notification

Current Date: 06-May-2021

TE Connectivity

Product Change Notification: E-21-004947

PCN Date: 05-MAY-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
CPC Connectors

Description of Changes
Delete the existing AMP logo molded into the housing. Add a molded TE logo close to the molded part number where possible. The molded TE logo and molded part number may be located on any flange edge of receptacles or body of plugs.

Reason for Changes:
Product Improvement. Change brand marking from AMP to TE. TE considers this a form change because the logos are external visible features of the parts.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	10-NOV-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-NOV-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
206037-1	NO		TYC206037-1	"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO		TYC206037-2				
206044-1	NO		TYC206044-1				
206137-1	NO		TYC206137-1				
206137-5	NO						
206151-1	NO		TYC206151-1				
206151-2	NO		TYC206151-2				
206151-3	NO		TYC206151-3, TYC8-1532247-0				
206306-1	NO		TYC206306-1				
206425-1	NO		TYC206425-1	"4-40001-7431"			
206430-1	NO		TYC206430-1				
206430-2	NO		TYC206430-2	"5011473", "CL0834-000", "JOR-06588"			
206613-1	NO		TYC206613-1				
206705-1	NO		TYC206705-1	"683370-000", "AMPS-0-0206705-1"			
206705-2	NO		TYC206705-2	"195902-000", "AMPS-0-0206705-2"			
206705-3	NO		TYC206705-3				
206705-4	NO		TYC206705-4				
207486-1	NO		TYC207486-1	"402697510"			
211401-1	NO		TYC211401-1				
211401-2	NO		TYC211401-2				
211401-3	NO		TYC211401-3				
211401-4	NO						
211769-1	NO		TYC211769-1				
211769-3	NO		TYC211769-3				
788155-2	NO		TYC788155-2				
788159-2	NO		TYC788159-2				
796274-1	NO		TYC796274-1				

