



Product Change Notification

Current Date: 14-May-2021

TE Connectivity

Product Change Notification: P-21-020923

PCN Date: 13-MAY-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

B-043's, B-044's, B-046's, D-148's, TDK-2X. W-040's

Description of Changes

To improve Manufacturability and consistency. OD and Height of solder change keeping the amount of solder (weight and volume) unchanged.

Reason for Changes:

Product improvement.To improved manufacturability.

Estimated Dates:
Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

13-MAY-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
405617-000	NO		RAY405617-000	1193061-4, B-044-24-N			
623158-000	NO		RAY623158-000	1194927-8, D-148-0202			
690152-000	NO		RAY690152-000	7-1199114-2, B-044-20-N			



Product Change Notification

Current Date: 14-May-2021

TE Connectivity

Product Change Notification: P-21-020923

PCN Date: 13-MAY-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

B-043's, B-044's, B-046's, D-148's, TDK-2X. W-040's

Description of Changes

To improve Manufacturability and consistency. OD and Height of solder change keeping the amount of solder (weight and volume) unchanged.

Reason for Changes:

Product improvement.To improved manufacturability.

Estimated Dates:
Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

13-MAY-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
405617-000	NO		RAY405617-000	1193061-4, B-044-24-N			