



02-Jul-2021

PCN #:PCN-21-106333

Subject:Product Discontinuance | KUIP Relays.

Description of Change: Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below in the last few years. To optimize TE's product portfolio, TE decided to obsolete (exit) KUIP of Potter & Brumfield Panel Plug-In Relays. TE is offering a last-time buy. TE requests you to consider the last-time buy order date and place your orders before the given date.

Reason: TE can offer close equivalents of standard catalog PN, if you need support in choosing catalog PN for your application, please reach out to your TE account manager. Considering low volume, custom and old tooling associated with this set of PNs, TE reserves right to not accept PO or reduce volume on accepted, for any reasons.

Key Dates:

Last Order Date:01-Oct-2021

Last Ship/EOL Date:08-Apr-2022

Product Affected	Alias Part Number
1-1393115-6	"KUIP-14D15-12"
2-1393115-1	"KUIP-5A55-240"
1393115-1	"KUIP-11A15-120"
1423342-1	"KUIP-11D15-12", "KUIP-11D15-12"
1393115-6	"KUIP-11D13-24"
2-1393115-2	"KUIP-7A55-24"
1-1393115-9	"KUIP-14D55-24"
8-1423996-4	"KUIP-14A55-120"
9-1393114-8	"KUIP-11AT5-120"
1393115-2	"KUIP-11A15-24"
1393115-7	"KUIP-11D15-24"

Product Affected	Alias Part Number
1-1393115-4	"KUIP-14A15-120"
1-1393115-7	"KUIP-14D15-24"
1393115-3	"KUIP-11A55-120"
1-1393115-1	"KUIP-11D55-24"
1-1393115-0	"KUIP-11D55-12"
1393115-5	"KUIP-11DT5-24"

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or

all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.