



Date: August 4, 2021

To: Banner Channel Partners

From: Steve Milbrath, Product Life Cycle Director  
Christian Olivares, Global Product Manager, Industrial Wireless

Re: Discontinuation Notice – Occupancy and Sanitation Solution Kits

---

Banner Engineering is issuing notification regarding the immediate inactivation of all industrial wireless Occupancy and Sanitation Solution Kits as well as related Finished Good kit items ( see attached table of affected models ). This action is driven by continuous evaluation and responses to very dynamic global and business changes that have made the continuation of these select models unnecessary.

Our Industrial Wireless Solution and Expansion Kits remain as released items for monitoring various asset parameters such as: Vibration, Temperature, Humidity, and Tank Level Monitoring.

Please ensure all your sales teams are aware of this product notice and contact your regional Banner sales team to discuss all your industrial wireless needs.

Thank You!

**Banner Engineering Corporation**

9714 Tenth Avenue North • Minneapolis, MN 55441 • Phone 763.544.3164 • Fax 763.544.3213 • [www.bannerengineering.com](http://www.bannerengineering.com)



ITEM	DESCRIPTION	PROD_FAM_DESC
810011	DX80N9Q45LPDIR	Q45 WIRELESS
810012	DX80N9Q45LPDIR NB	Q45 WIRELESS
810013	DX80N2Q45LPDIR	Q45 WIRELESS
810014	DX80N2Q45LPDIR NB	Q45 WIRELESS
810030	OSK9-1TC	SOLUTIONS KIT
810031	OSK2-1TC NB	SOLUTIONS KIT
810032	OSK9-2TC	SOLUTIONS KIT
810033	OSK2-2TC-NB	SOLUTIONS KIT
810034	OSK9-4TC	SOLUTIONS KIT
810035	OSK2-4TC-NB	SOLUTIONS KIT
810036	OSK9-2MC	SOLUTIONS KIT
810037	OSK2-2MC-NB	SOLUTIONS KIT
810038	OSK9-4MC	SOLUTIONS KIT
810039	OSK2-4MC-NB	SOLUTIONS KIT
810115	SSK9-4CT	SOLUTIONS KIT
810116	SSK2-4CT-NB	SOLUTIONS KIT
810117	SSK9-4SA	SOLUTIONS KIT
810118	SSK2-4SA-NB	SOLUTIONS KIT
810350	DX80N9X2W-DIR	DX80 PERFORMANCE
810351	DX80N9X2W-DIR NB	DX80 PERFORMANCE
810352	DX80N2X2W-DIR	DX80 PERFORMANCE
810353	DX80N2X2W-DIR NB	DX80 PERFORMANCE
810354	DX80N <sub>w</sub> X2W-DIRE	DX80 PERFORMANCE
810355	DX80N <sub>w</sub> X2W-DIRE NB	DX80 PERFORMANCE
810356	DX80N9X2W-DIRR	DX80 PERFORMANCE
810357	DX80N9X2W-DIRR NB	DX80 PERFORMANCE
810358	DX80N2X2W-DIRR	DX80 PERFORMANCE
810359	DX80N2X2W-DIRR NB	DX80 PERFORMANCE
810360	OSK9-1TCER	SOLUTIONS KIT
810361	OSK2-1TCER-NB	SOLUTIONS KIT
810362	OSK9-2TCER	SOLUTIONS KIT
810363	OSK2-2TCER-NB	SOLUTIONS KIT
810364	OSK9-4TCER	SOLUTIONS KIT
810365	OSK2-4TCER-NB	SOLUTIONS KIT
810366	OSK9-2MCER	SOLUTIONS KIT
810367	OSK2-2MCER-NB	SOLUTIONS KIT
810368	OSK9-4MCER	SOLUTIONS KIT
810369	OSK2-4MCER-NB	SOLUTIONS KIT
810620	DXM1200-B1R1-OSK9-TCER	DXM SERIES
810621	DXM1200-B1R3-OSK2-TCER	DXM SERIES
810622	DXM1200-B1R1-OSK9-MCER	DXM SERIES
810623	DXM1200-B1R3-OSK2-MCER	DXM SERIES

Table 1: Models to be Discontinued

Banner Engineering Corporation

9714 Tenth Avenue North • Minneapolis, MN 55441 • Phone 763.544.3164 • Fax 763.544.3213 • [www.bannerengineering.com](http://www.bannerengineering.com)