



# Product Change Notification

Current Date: 24-Sep-2021

## TE Connectivity

**Product Change Notification:** P-21-021485

**PCN Date:** 23-SEP-21

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Power F change to alternative contact material

### Description of Changes

Dear customer, due to the COVID-19 epidemic, our contact rivet supplier (DODUCO Spain) has insufficient supply capacity, we are forced to produce the following PNs with alternative Tanaka rivets: 8-1414939-3 (POWER F CONTACT E-CU/AGSNO2 SIE21DK C166) and 8-1414939-4 (POWER F CONTACT E-CU/AGSNO2 SIE21DK C167). The alternative contact rivets from Tanaka are already used in big quantities for various similar relays since years. All the deliveries produced with this change will be recorded and identified to assure proper traceability in the future. This PCN is only for information purpose. There is no change in form, fit or function and no drawing change. An approval is not required. TE Connectivity Sales Team will answer your questions on any additional information or clarification that may be needed in that respect.

### Reason for Changes:

Product improvement. To avoid stopping production due to lack of material rivets 3-1414970-0 (POWER F CONTACT E-CU/AGSNO2 TOS 12F C363) and 9-1414979-6 (POWER F CONTACT E-CU/AGSNO2 TOS 12F C364).

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	27-SEP-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	31-DEC-2021

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393303-7</a>	NO			"V23134B 52X372"			
<a href="#">1393303-8</a>	NO		TYC1393303-8	"V23134B 52X372 * B"			
<a href="#">3-1393303-4</a>	NO		TYC3-1393303-4	"V23134B1052C642"			
<a href="#">3-1393303-7</a>	NO		TYC3-1393303-7	"V23134B1053C642"			
<a href="#">5-1393304-2</a>	NO		TYC5-1393304-2	"V23134K 59X312", "V23134K0059X312"			
<a href="#">7-1393302-5</a>	NO		TYC7-1393302-5	"V23134B 52C642"			



# Product Change Notification

Current Date: 24-Sep-2021

## TE Connectivity

**Product Change Notification:** P-21-021485

**PCN Date:** 23-SEP-21

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Power F change to alternative contact material

### Description of Changes

Dear customer, due to the COVID-19 epidemic, our contact rivet supplier (DODUCO Spain) has insufficient supply capacity, we are forced to produce the following PNs with alternative Tanaka rivets: 8-1414939-3 (POWER F CONTACT E-CU/AGSNO2 SIE21DK C166) and 8-1414939-4 (POWER F CONTACT E-CU/AGSNO2 SIE21DK C167). The alternative contact rivets from Tanaka are already used in big quantities for various similar relays since years. All the deliveries produced with this change will be recorded and identified to assure proper traceability in the future. This PCN is only for information purpose. There is no change in form, fit or function and no drawing change. An approval is not required. TE Connectivity Sales Team will answer your questions on any additional information or clarification that may be needed in that respect.

### Reason for Changes:

Product improvement. To avoid stopping production due to lack of material rivets 3-1414970-0 (POWER F CONTACT E-CU/AGSNO2 TOS 12F C363) and 9-1414979-6 (POWER F CONTACT E-CU/AGSNO2 TOS 12F C364).

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	27-SEP-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	31-DEC-2021

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">3-1393303-4</a>	NO		TYC3-1393303-4	"V23134B1052C642"			