



Product Change Notification

Current Date: 14-Oct-2021

TE Connectivity

Product Change Notification: P-21-021583

PCN Date: 13-OCT-21

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

SR4M/D & SR6 relay series

Description of Changes

TE's SR4 & SR6 Force Guided Relay series have regained REACH compliance without exemptions.

Reason for Changes:

Document clarification. We previously reported in April 2020 that these products contained SVHC BPA above the REACH threshold of 0,1%. This was based on an updated material declaration from our supplier of the terminal sealing adhesive in its liquid state, as delivered to us. We have now found out, that the majority of this SVHC vanishes during chemical reactions while the adhesive is cured. After curing, which represents the state in which all our relays are shipped, the content of SVHC BPA is below the REACH threshold of 0,1% and therefore the relays are REACH compliant without exemptions. Our Statements of Compliance for the relays have been updated accordingly and are linked to the affected products on TE.com. We assume, that this threshold was actually never surpassed on our finished product since the terminal sealing adhesive was introduced in September 2017.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

14-OCT-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-0	NO			"V23050-A1048-A542", "V23050A1048A542"			
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1-1415015-1	NO			"V23050-A1012-A533", "V23050A1012A533"			
1-1415017-1	NO			"V23050-A1012-A551", "V23050A1012A551"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415017-1	NO			"V23050-A1024-A551", "V23050A1024A551"			
1415055-1	NO			"SR4D4012"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415055-1	NO			"SR4D4024"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415053-1	NO			"SR4M4005"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-1	NO			"SR6A6K12"			
6-1415537-3	NO			"SR6A6K18"			
6-1415537-5	NO			"SR6A6K24"			
7-1415018-1	NO			"V23050-A1060-A533", "V23050A1060A533"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7-1415054-1	NO			"SR4D4005"			
7-1415359-1	NO			"V23050A1110A533X01"			
8-1415053-1	NO			"SR4M4012"			
8-1415535-1	NO			"SR9400003"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			
9-1415053-1	NO			"SR4M4018"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-0	NO		TYC1-1393260-0	"V23050-A1048-A542", "V23050A1048A542"			
1-1415015-1	NO		TYC1-1415015-1	"V23050-A1012-A533", "V23050A1012A533"			
1-1415017-1	NO		TYC1-1415017-1	"V23050-A1012-A551", "V23050A1012A551"			
1393260-7	NO		TYC1393260-7	"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO		TYC1415015-1	"V23050-A1024-A533", "V23050A1024A533"			
1415017-1	NO		TYC1415017-1	"V23050-A1024-A551", "V23050A1024A551"			
1415055-1	NO		TYC1415055-1	"SR4D4012"			
3-1415018-1	NO		TYC3-1415018-1	"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO		TYC3-1415054-1	"SR4M4048"			
3-1415055-1	NO		TYC3-1415055-1	"SR4D4024"			
3-1415353-1	NO		TYC3-1415353-1	"SR6M4024"			
4-1415053-1	NO		TYC4-1415053-1	"SR4M4024"			
5-1415053-1	NO		TYC5-1415053-1	"SR4M4005"			
6-1415055-1	NO		TYC6-1415055-1	"SR4D4048"			
6-1415537-1	NO		TYC6-1415537-1	"SR6A6K12"			
6-1415537-3	NO		TYC6-1415537-3	"SR6A6K18"			
6-1415537-5	NO		TYC6-1415537-5	"SR6A6K24"			
7-1415018-1	NO		TYC7-1415018-1	"V23050-A1060-A533", "V23050A1060A533"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7- 1415054- 1	NO		TYC7-1415054-1	"SR4D4005"			
8- 1415053- 1	NO		TYC8-1415053-1	"SR4M4012"			
8- 1415535- 1	NO		TYC8-1415535-1	"SR9400003"			
9- 1415018- 1	NO		TYC9-1415018-1	"V23050-A1110-A533", "V23050A1110A533"			
9- 1415053- 1	NO		TYC9-1415053-1	"SR4M4018"			

Customer: Shanghai TTI Electronics Co Ltd (1405773)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 1393260- 3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1- 1415015- 1	NO			"V23050-A1012-A533", "V23050A1012A533"			
1415015- 1	NO			"V23050-A1024-A533", "V23050A1024A533"			
6- 1415537- 1	NO			"SR6A6K12"			
6- 1415537- 5	NO			"SR6A6K24"			

Customer: TTI Hong Kong Ltd (3267887)

Location: Fanling

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393260- 4	NO			"V23050-A1012-A542", "V23050A1012A542"			

Customer: TTI Electronics Asia Pte Ltd. (1407161)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 1393260- 3	NO			"V23050-A1110-A542", "V23050A1110A542"			
6- 1415537- 1	NO			"SR6A6K12"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1415015-1	NO		TYC1-1415015-1	"V23050-A1012-A533", "V23050A1012A533"			
1-1415017-1	NO		TYC1-1415017-1	"V23050-A1012-A551", "V23050A1012A551"			
1-1415017-1	NO		TYC1415017-1	"V23050-A1024-A551", "V23050A1024A551"			
3-1415018-1	NO		TYC3-1415018-1	"V23050-A1021-A533", "V23050A1021A533"			
3-1415055-1	NO		TYC3-1415055-1	"SR4D4024"			
3-1415353-1	NO		TYC3-1415353-1	"SR6M4024"			
4-1415053-1	NO		TYC4-1415053-1	"SR4M4024"			
5-1415053-1	NO		TYC5-1415053-1	"SR4M4005"			
6-1415537-1	NO		TYC6-1415537-1	"SR6A6K12"			
6-1415537-3	NO		TYC6-1415537-3	"SR6A6K18"			
7-1415054-1	NO		TYC7-1415054-1	"SR4D4005"			
8-1415053-1	NO		TYC8-1415053-1	"SR4M4012"			
9-1415018-1	NO		TYC9-1415018-1	"V23050-A1110-A533", "V23050A1110A533"			

Customer: Shanghai TTI Electronics Co Ltd (3064990)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1415015-1	NO			"V23050-A1012-A533", "V23050A1012A533"			
1-1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
6-1415537-1	NO			"SR6A6K12"			
6-1415537-5	NO			"SR6A6K24"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393260-Z-3-1415055-1	NO			"V23050-A1024-A542", "V23050A1024A542"			
Z-1415054-1	NO			"SR4D4024"			
Z-1415359-1	NO			"SR4D4005"			
Z-1415359-1	NO			"V23050A1110A533X01"			