



Expertise Applied | Answers Delivered

Littelfuse, Inc.
8755 West Higgins Road, Suite 500
Chicago, IL 60631 USA
(773) 628-1000

Subject: SE-601 and SE-70X Series Temporary Faceplate and Switch Changes
Document: LFPCN_RC00056
Date Released: October 25, 2021

Dear Valued Customer,

This letter is to inform you of two temporary changes to the SE-601 and SE-70X series product lines. Effective immediately, products listed below may include a grey faceplate insert and grey selector switches, as shown in the photos below. This change is temporary, and the products will revert to the original black faceplate insert and black selector switches when supplies permit. There is no change to the product operation or certification.

The following products are affected:

SE-601-0D	SE-701-03	SE-701-0U	SE-703-0T-00	SE-704-0D
SE-601-0D-CC	SE-701-03-CC	SE-701-0U-CC	SE-703-0T-02	SE-704-0D-CC
SE-601-0T	SE-701-0D	SE-703-03-00	SE-703-0U-00	SE-704-0T
SE-601-0T-CC	SE-701-0D-CC	SE-703-03-02	SE-703-0U-02	SE-704-0T-CC
SE-601-0U	SE-701-0T	SE-703-0D-00	SE-704-03	SE-704-0U
SE-601-0U-CC	SE-701-0T-CC	SE-703-0D-02	SE-704-03-CC	SE-704-0U-CC



Black Faceplate Insert



Grey Faceplate Insert



Black Selector Switch



Grey Selector Switch

Please call or email Littelfuse Technical Support at relays@littelfuse.com or 800-832-3873 if you have any questions.

Sincerely,

Mark Pollock, P.Eng.
Global Product Manager
Industrial Business Unit
Littelfuse, Inc.