



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001046

DATE: 29-Nov-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1845E-100+	N/A	31-May-2022	27-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX203CWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203CWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203ECWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EEWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EEWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX233ACWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3233ECWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3233ECWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235ECWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235ECWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235EEWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235EEWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	TMC-00-0145	TMC-00-0188	29-Nov-2021	27-Nov-2022	Part can no longer be manufactured
Discontinuance	TMC-40-0120	TMC-40-0196	29-Nov-2021	27-Nov-2022	EVKIT is No Longer Supported
Discontinuance	TMC-40-0149	TMC-40-0200	29-Nov-2021	27-Nov-2022	EVKIT is No Longer Supported
Discontinuance	TMC8462-BA	TMC8462A-BA	29-Nov-2021	27-Nov-2022	Part can no longer be manufactured
Discontinuance	TMC8462-BOB-ETH	TMC8462A-BOB-ETH	29-Nov-2021	27-Nov-2022	Part can no longer be manufactured
Discontinuance	TMC8462-EVAL	TMC8462A-EVAL	29-Nov-2021	27-Nov-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 30-Dec-2021