

EOL NOTIFICATION

NOTIFICATION DATE	Jun 28, 2021
SUBJECT	EOL of various Sound I MEMS Microphones
PRODUCTS AFFECTED	<p>Part No: ICS-40740 ICS-40180 ICS-40181 INMP404ACEZ-R0 INMP404ACEZ-R7 ICS-51360 ICS-41352 MMICT3904-00-012</p> <p>EV Board Part No: EV_IC3-40740-FX EV_IC3-40180-FX EV_IC3-40181-FX EV_INMP404-FX EV_IC3-51360-FX EV_IC3-41352-FX EV_T3904-FX</p>
REASON FOR CHANGE	As part of TDK's on-going product lifecycle management process, the listed components will be discontinued. Please contact your local Sales office for alternative options.
DESCRIPTION OF CHANGE	Product discontinuance notice for components listed
LAST TIME BUY (LTB)	Dec 11, 2021
LAST TIME SHIP (LTS)	Mar 30, 2022
ALTERNATE DEVICE	
ADDITIONAL INFORMATION	
<p>Should you have any issues with the timeline or content of this change, please send email to pcn@invensense.com. No response from customers within 30 days of the initial notification date herein will be deemed as acceptance of the change and the change will be implemented pursuant to the Planned Implementation date set forth in this PCN.</p> <p>Information in this document is provided in connection with InvenSense, Inc. ("InvenSense") products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in InvenSense's Terms and Conditions of Sale for such products, InvenSense assumes no liability whatsoever, and InvenSense disclaims any express or implied warranty, relating to sale and/or use of InvenSense products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. InvenSense products are not intended for use in medical, life saving, or life sustaining applications.</p>	

