

17-Dec-2021

PCN #: P-21-021923

Subject: Mini K HV Product Family - V23700-xxxxx-xxxx - All

Description of Change : Dear Customer,

We hereby inform you that our current copper material supplier has currently no capacity to supply us and present a backlog of near 6 months.

In order to fulfil our commitments with our customers we have approved the usage of a second source for relay spring from an alternative supplier. This alternative supplier is already approved for automotive industry and supplies our plant with material for similar relays.

The material from the alternative suppliers complies with general specifications (UNS C17200, ISO CuBe2, or JIS 1720) and also our internal material specification TEC-100-238. This change is nor a Form Fit Function and all product requirements are fulfilled.

This is only a Informative PCN with no need to be released from customer side. We appeal for your understanding, but right now it is the only possible alternative to avoid stoppages in our production line and at our customers.

Reason: Product improvement. This situation is related to failures in the copper raw material supply chain that are severely and transversally affecting the entire automotive industry.

The supplier is unable to meet the deadlines and quantities previously agreed with TE.

Key Dates:

Contact By Date:03-Jan-2022 Implementation Date:03-Jan-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
2-1904058-5	"V23700- C0001-A408"		
8-1904105-1	"V23700- F0002-X001"		
2-1904058-6	"V23700- F0001-A408"		
2-1904112-2			

8-1904105-2	"V23700- F0002-X001"	
2-1904058-7	"V23700- F0002-A408"	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.