



# Product Change Notification

Current Date: 20-Dec-2021

## TE Connectivity

**Product Change Notification:** P-21-021905

**PCN Date:** 16-DEC-21

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

The listed part numbers are being discontinued and no longer available. Please consult with your local customer sales.

### Description of Changes

The listed part numbers below will be discontinued and no longer available.

### Reason for Changes:

Part status change. The listed part numbers below will be discontinued and no longer available.

### Estimated Dates:

**Last Order Date** (Obsolete Parts Only):

**First Date To Ship** (Changed Parts Only):

14-JAN-2022

**Last Ship Date** (Obsolete Parts Only):

**Last Date for Mixed Shipments:** (Changed Parts Only):

31-JUL-2022

No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1053241-1</a>	NO		TYC1053241-1	"2058-5219-00"			
<a href="#">1057679-1</a>	NO		TYC1057679-1	"3104-7985-00"			
<a href="#">2-1393589-0</a>	NO		TYC2-1393589-0	"C42334A 347A103", "C42334A347A103"			
<a href="#">5207719-3</a>	NO		5727584-7, TYC5207719-3				
<a href="#">6274425-2</a>	NO		TYC6274425-2				



# Product Change Notification

Current Date: 20-Dec-2021

## TE Connectivity

**Product Change Notification:** P-21-021905

**PCN Date:** 16-DEC-21

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

The listed part numbers are being discontinued and no longer available. Please consult with your local customer sales.

### Description of Changes

The listed part numbers below will be discontinued and no longer available.

### Reason for Changes:

Part status change. The listed part numbers below will be discontinued and no longer available.

### Estimated Dates:

**Last Order Date** (Obsolete Parts Only):

14-JAN-2022

**First Date To Ship** (Changed Parts Only):

**Last Ship Date** (Obsolete Parts Only):

31-JUL-2022

**Last Date for Mixed Shipments:** (Changed Parts Only):

No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1050720-1</a>	NO		TYC1050720-1				
<a href="#">1051081-1</a>	NO		TYC1051081-1				
<a href="#">1051638-1</a>	NO		TYC1051638-1, GC810CB2				
<a href="#">1052552-1</a>	NO		TYC1052552-1	"2052-1352-02"			
<a href="#">1053241-1</a>	NO		TYC1053241-1	"2058-5219-00"			
<a href="#">1057290-1</a>	NO		TYC1057290-1	"3052-1201-10"			
<a href="#">1057679-1</a>	NO		TYC1057679-1	"3104-7985-00"			
<a href="#">1058058-1</a>	NO		TYC1058058-1	"3280-2240-00"			
<a href="#">1058651-1</a>	NO		TYC1058651-1	"3680-2240-00"			
<a href="#">1059402-1</a>	NO		TYC1059402-1	"4503-7941-00"			
<a href="#">1059617-1</a>	NO		TYC1059617-1	"4557-5009-02"			
<a href="#">1059716-1</a>	NO		TYC1059716-1				
<a href="#">1059729-1</a>	NO		TYC1059729-1	"4584-2240-02"			
<a href="#">1059919-1</a>	NO		TYC1059919-1	"4763-0000-00"			
<a href="#">1274584-1</a>	NO		TYC1274584-1				
<a href="#">1310852-1</a>	NO		TYC1310852-1				
<a href="#">1408152-1</a>	NO		TYC1408152-1				
<a href="#">193839-2</a>	NO		TYC193839-2				
<a href="#">193839-3</a>	NO						
<a href="#">193839-4</a>	NO		TYC193839-4				
<a href="#">2-1393589-0</a>	NO		TYC2-1393589-0	"C42334A 347A103", "C42334A347A103"			
<a href="#">2-1437012-8</a>	NO		TYC2-1437012-8	"609-007-1"			
<a href="#">2-329940-1</a>	NO		TYC2-329940-1				
<a href="#">201146-9</a>	NO						
<a href="#">221221-7</a>	NO		TYC221221-7	"4-27051-0905"			
<a href="#">227079-5</a>	NO		TYC227079-5				
<a href="#">227079-6</a>	NO		TYC227079-6				
<a href="#">415377-1</a>	NO		TYC415377-1				
<a href="#">448435-2</a>	NO		TYC448435-2				
<a href="#">5207719-3</a>	NO		5727584-7, TYC5207719-3				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5207871-1</a>	NO		TYC5207871-1				
<a href="#">5221128-1</a>	NO		TYC5221128-1				
<a href="#">5225398-7</a>	NO		TYC5225398-7				
<a href="#">5413959-3</a>	NO		TYC5413959-3				
<a href="#">5414946-5</a>	NO		TYC5414946-5				
<a href="#">5415226-1</a>	NO		TYC5415226-1				
<a href="#">6274425-2</a>	NO		TYC6274425-2				