



Product Change Notification

Current Date: 22-Dec-2021

TE Connectivity

Product Change Notification: P-21-021935

PCN Date: 20-DEC-21

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

The PNs listed below will remain as ACTIVE status and will not be discontinued.

Description of Changes

This PCN is to revise an error previously released on PCN numbers: P-21-021901，P-21-021902，P-21-021903，P-21-021904，P-21-021905，P-21-021906，P-21-021907，P-21-021908，P-21-021909，P-21-021910，P-21-021911。 The PNs listed below will remain as ACTIVE status and will not be discontinued. These PNs were previously listed on a PCN for discontinuance in error. We sincerely apologize for any confusion this may have caused. Thank you.

Reason for Changes:

Document clarification.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393589-8	NO			"C42334A 347A102", "C42334A347A102"			
1-1437012-0	NO			"609-003"			
1-5745172-3	NO			"010-6840-00"			
1393481-1	NO			"V23529B1225B215"			
1393481-5	NO			"V23529B1225C209"			
1648325-1	NO			"702-92-01109"			
1766194-1	NO						
1766484-1	NO						
193839-1	NO						
193839-2	NO						
193839-3	NO						
194189-8	NO						
2-1393560-1	NO			"V42254A 132V 1"			
2-1393560-5	NO			"V42254A 142V 1"			
2-1393560-8	NO			"V42254A 152V 2"			
2-1393561-4	NO			"V42254A 261V 18"			
2-1393561-5	NO			"V42254A 261V 19"			
2-1393589-0	NO			"C42334A 347A103", "C42334A347A103"			
2-1437012-4	NO			"609-006-1"			
2-1437012-8	NO			"609-007-1"			
2-5745174-7	NO						
205734-5	NO						
215072-2	NO						
338170-2	NO						
5-106507-2	NO						
5-338168-2	NO						
5-338309-2	NO						
5-338313-2	NO						
5-338314-2	NO						
5-338315-2	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5205734-7	NO						
5205980-4	NO						
5205980-5	NO						
5207719-3	NO		5727584-7				
5207871-1	NO						
5745833-1	NO						
5745833-5	NO						
5745854-1	NO						
5745854-3	NO						
5745854-5	NO						
5746881-1	NO			"2-42934-1478"			
5746881-2	NO						
5747099-1	NO						
5747099-3	NO						
5747099-5	NO						
5747100-1	NO						
5747100-3	NO						
6648428-1	NO						
7-745129-0	NO						
7-745129-2	NO						
7-745129-4	NO						
7-745129-6	NO						
749087-2	NO						
749805-7	NO						
749806-7	NO						
749806-9	NO						
750644-1	NO						
750831-1	NO			"673-1091-01"			
750831-2	NO						
829068-1	NO						
9-1393480-9	NO			"V23529B1225B209"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gerlninden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393589-8	NO		TYC1-1393589-8	"C42334A 347A102", "C42334A347A102"			
1-1437012-0	NO		TYC1-1437012-0	"609-003"			
1-5745172-3	NO		TYC1-5745172-3(BU), TYC1-5745172-3	"010-6840-00"			
1393481-1	NO		TYC1393481-1	"V23529B1225B215"			
1393481-5	NO		TYC1393481-5	"V23529B1225C209"			
1648325-1	NO		TYC1648325-1	"702-92-01109"			
1766484-1	NO						
193839-2	NO		TYC193839-2				
193839-3	NO						
2-1393560-1	NO		TYC2-1393560-1	"V42254A 132V 1"			
2-1393560-5	NO		TYC2-1393560-5	"V42254A 142V 1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1393560-8	NO		TYC2-1393560-8	"V42254A 152V 2"			
2-1393561-4	NO		TYC2-1393561-4	"V42254A 261V 18"			
2-1393561-5	NO		TYC2-1393561-5	"V42254A 261V 19"			
2-1393589-0	NO		TYC2-1393589-0	"C42334A 347A103", "C42334A347A103"			
2-1437012-8	NO		TYC2-1437012-8	"609-007-1"			
215072-2	NO		TYC215072-2				
338170-2	NO		TYC338170-2				
5-106507-2	NO		TYC5-106507-2				
5-338168-2	NO		TYC5-338168-2				
5-338309-2	NO		TYC5-338309-2				
5-338313-2	NO		TYC5-338313-2				
5-338314-2	NO		TYC5-338314-2				
5-338315-2	NO		TYC5-338315-2				
5205980-4	NO		TYC5205980-4				
5205980-5	NO		TYC5205980-5				
5207719-3	NO		5727584-7, TYC5207719-3				
5207871-1	NO		TYC5207871-1				
5746881-1	NO		TYC5746881-1	"2-42934-1478"			
5747099-1	NO						
5747099-3	NO		TYC5747099-3				
6648428-1	NO		TYC6648428-1				
7-745129-0	NO						
7-745129-2	NO		TYC7-745129-2				
7-745129-4	NO		TYC7-745129-4				
7-745129-6	NO		TYC7-745129-6				
749087-2	NO		TYC749087-2				
749806-7	NO		TYC749806-7				
750644-1	NO						
750831-1	NO		TYC750831-1	"673-1091-01"			
750831-2	NO		TYC750831-2				
829068-1	NO		TYC829068-1				
9-1393480-9	NO		TYC9-1393480-9	"V23529B1225B209"			

Customer: TTI Electronics Asia Pte Ltd. (1407161)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-5745172-3	NO			"010-6840-00"			
1-5745172-3	NO			"010-6840-00"			
2-1393561-4	NO			"V42254A 261V 18"			
5746881-2	NO						

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393589-8	NO		TYC1-1393589-8	"C42334A 347A102", "C42334A347A102"			
1-5745172-3	NO		TYC1-5745172-3(BU), TYC1-5745172-3	"010-6840-00"			
1393481-5	NO		TYC1393481-5	"V23529B1225C209"			
1648325-1	NO		TYC1648325-1	"702-92-01109"			
2-1393560-1	NO		TYC2-1393560-1	"V42254A 132V 1"			
2-1393560-5	NO		TYC2-1393560-5	"V42254A 142V 1"			
2-1393561-4	NO		TYC2-1393561-4	"V42254A 261V 18"			
2-1393589-0	NO		TYC2-1393589-0	"C42334A 347A103", "C42334A347A103"			
5-338315-2	NO		TYC5-338315-2				
5205980-4	NO		TYC5205980-4				
5205980-5	NO		TYC5205980-5				
5207719-3	NO		TYC5207719-3				
6648428-1	NO		TYC6648428-1				
7-745129-2	NO		TYC7-745129-2				
749087-2	NO		TYC749087-2				

Customer: Shanghai TTI Electronics Co Ltd (3064990)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5745854-1	NO						

Customer: Tti Inc (3065242)

Location: Maisach-Gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5205980-4	NO						

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: TTI003

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1437012-0	NO			"609-003"			
1-5745172-3	NO			"010-6840-00"			
1648325-1	NO			"702-92-01109"			
1766194-1	NO						
193839-1	NO						
193839-2	NO						
193839-3	NO						
194189-8	NO						
2-1437012-4	NO			"609-006-1"			
2-1437012-8	NO			"609-007-1"			
2-5745174-7	NO						
205734-5	NO						
5205734-7	NO						
5205980-4	NO						
5205980-5	NO						
5207719-3	NO		5727584-7				
5207871-1	NO						
5745833-1	NO						
5745833-5	NO						
5745854-1	NO						
5745854-3	NO						
5745854-5	NO						
5746881-1	NO			"2-42934-1478"			
5746881-2	NO						
5747099-1	NO						
5747099-5	NO						
5747100-1	NO						
5747100-3	NO						
749087-2	NO						
749805-7	NO						
749806-7	NO						
749806-9	NO						
750644-1	NO						

Customer: Shanghai TTI Electronics Co Ltd (1405773)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5745854-1	NO						

Customer: TTI Inc (3221065)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5205980-5	NO						

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 5745172-3	NO			"010-6840-00"			
193839-1	NO						
193839-2	NO						
2- 1393561-4	NO			"V42254A 261V 18"			
5745833-5	NO						
5746881-2	NO						
5747100-1	NO						
7-745129- 6	NO						

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 5745172-3	NO			"010-6840-00"			
193839-1	NO						
193839-2	NO						
2- 1393561-4	NO			"V42254A 261V 18"			
5745833-5	NO						
5746881-2	NO						
5747100-1	NO						
7-745129- 6	NO						