




Product Change Notification (PCN)

PCN Number	510048	Date Issued	March 19, 2021
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	March 19, 2021		
Sample Availability Date (Changed Part)	March 19, 2021		
Planned Implementation Date	April 30, 2021		
Method of Identifying Change	No special marking on the product or packaging		

Before Change

Change Point : Plating information and Part number



After Change

Summary

- We found there are some typo on 5054330003-SD. We notify about correcting the following misdescription on the drawing.
There is no change to the product itself, so there is no impact to Form, Fit or Function.
- Objective Drawing number: 5054330003-SD PSD 000
 - Current Revision: Rev. A
 - After Revision: Rev. B
- Change point on the drawing

Change point	Current description	After description
Plating of Terminal	MATTE TIN-BISMUTH PLATING	GOLD PLATING
Under Plating of Terminal	1.0 micro-meter MINIMUM	2.0 micro-meter MINIMUM
Part Number	505433 **7*, 505433 **8*	505433 **6*, 505433 **2*, 505433 **4*, 505433 **9*, 505433 **3*, 505433 **5*,



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510048**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com