

Product Change Notification (PCN)

PCN Number

508941

Date Issued

June 03, 2020

Reason for Change

Change to Product

Change Type Description

This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.

Assessment of Change

First article inspection

Internal Molex Qualification Date

January 18, 2021

Sample Availability Date (Changed Part)

January 18, 2021

Planned Implementation Date


January 18, 2021

Method of Identifying Change

Product made after planned implementation date can contain the change

Before Change

Before the change. Tape present between assembly and inner jacket



After Change

- Overview

 After removal of PET tape over assembly, between cores and inner jacket.
- Product Impact

 Profinet Cable

 no impact to fit, form or function

 Braid shield

 Al/PET tape

 Inner jacket

 Qualification Reports and samples available upon request after the date shown above and at first production of purchase order.



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:508941" in the e-mail Subject line for faster response.



Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com