

TDK Corporation

MAGNETICS BG

GM

Teppei Watanabe

HF-ACB/ACC series Product Discontinuation Notice

First of all, we would like to thank you very much for your continuous cooperation with TDK and our products.

Nowadays, we are in rapid change in circumstances surrounding products.

To overcome this situation, we have standardized, eliminated and consolidated of our items to improve profitability.

But then, this goods trading with you is difficult to treat.

Following is list of items stopped production this time.

Description

Your product name	Our product name	Our substitute
CB70-0805	HF30ACB201209-T	MMZ1608D050CTA00
CB70-0805-SCI	HF30ACB201209-T	MMZ1608D050CTA00
HF30ACB201209-T	HF30ACB201209-T	MMZ1608D050CTA00
HF30ACB201209-TD25	HF30ACB201209-TD25	MMZ1608D050CTD25
CB70-1206	HF30ACB321611-T	MMZ1608D220CTAH0
CB70-1206-SCI	HF30ACB321611-T	MMZ1608D220CTAH0
HF30ACB321611-T	HF30ACB321611-T	MMZ1608D220CTAH0
HF30ACB321611-TD25	HF30ACB321611-TD25	MMZ1608D220CTDH5
CB70-1210	HF30ACB322513-T	MMZ1608D500CTAH0
CB70-1210-SCI	HF30ACB322513-T	MMZ1608D500CTAH0
HF30ACB322513-T	HF30ACB322513-T	MMZ1608D500CTAH0
HF30ACB322513-TD25	HF30ACB322513-TD25	MMZ1608D500CTDH5

Discontinued products : See the table above

- Last order date : **March 31, 2023**

- Last shipment date : **October 31, 2023**

Please send an acknowledgement of receipt to your TDK sales representative, who is eager to help out with your need for substitutes or bulk orders.

Accept

Company

Department

Name

DISTRIBUTION

[illegible]

Accept

Company

Department

Name

DISTRIBUTION

Your product name	Our product name	Our substitute
CB70-1812	HF30ACB453215-T	MMZ1608D800CTAH0
HF30ACB453215-T	HF30ACB453215-T	MMZ1608D800CTAH0
HF30ACB453215-TD25	HF30ACB453215-TD25	MMZ1608D800CTDH5
HF30ACC201209-T	HF30ACC201209-T	MMZ1608D050CTA00
HF30ACC201209-TD25	HF30ACC201209-TD25	MMZ1608D050CTD25
HF30ACC321611-T	HF30ACC321611-T	MMZ1608D220CTAH0
HF30ACC321611-TD25	HF30ACC321611-TD25	MMZ1608D220CTDH5
651080-004	HF30ACC322513-T	MPZ2012S300AT000
HF30ACC322513-T	HF30ACC322513-T	MPZ2012S300AT000
HF30ACC322513-TD25	HF30ACC322513-TD25	MPZ2012S300ATD25
HF30ACC453215-T	HF30ACC453215-T	MPZ1608D600BTA00
HF30ACC453215-TD25	HF30ACC453215-TD25	MPZ1608D600BTD25
HF30ACC575018-T	HF30ACC575018-T	MPZ2012S101AT000
HF30ACC575032-T	HF30ACC575032-T	MPZ2012S221AT000
HF30ACC635050-T	HF30ACC635050-T	MPZ2012S601AT000
CB50-0805	HF50ACB201209-T	MMZ1608S400ATA00
CB50-0805-SCI	HF50ACB201209-T	MMZ1608S400ATA00
HF50ACB201209-T	HF50ACB201209-T	MMZ1608S400ATA00
HF50ACB201209-TD25	HF50ACB201209-TD25	MMZ1608S400ATD25
CB50-1206	HF50ACB321611-T	MMZ1608S400ATA00
CB50-1206-SCI	HF50ACB321611-T	MMZ1608S400ATA00
HF50ACB321611-T	HF50ACB321611-T	MMZ1608S400ATA00
HF50ACB321611-TD25	HF50ACB321611-TD25	MMZ1608S400ATD25
CB50-1210	HF50ACB322513-T	MMZ1608S800ATA00
CB50-1210-SCI	HF50ACB322513-T	MMZ1608S800ATA00
HF50ACB322513-T	HF50ACB322513-T	MMZ1608S800ATA00
HF50ACB322513-TD25	HF50ACB322513-TD25	MMZ1608S800ATD25
852-3001-024	HF50ACB453215-T	MMZ1608S121ATA00
CB50-1812	HF50ACB453215-T	MMZ1608S121ATA00
HF50ACB453215-T	HF50ACB453215-T	MMZ1608S121ATA00
HF50ACB453215-TD25	HF50ACB453215-TD25	MMZ1608S121ATD25
HF50ACB453215-T/4	HF50ACB453215-TL	MMZ1608S121ATA00
HF50ACC201209-T	HF50ACC201209-T	MPZ2012S300AT000
HF50ACC201209-TD25	HF50ACC201209-TD25	MPZ2012S300ATD25
651080-001	HF50ACC321611-T	MPZ2012S300AT000
HF50ACC321611-T	HF50ACC321611-T	MPZ2012S300AT000
HF50ACC321611-TD25	HF50ACC321611-TD25	MPZ2012S300ATD25
HF50ACC322513-T	HF50ACC322513-T	MPZ2012S101AT000
HF50ACC322513-TD25	HF50ACC322513-TD25	MPZ2012S101ATD25
HF50ACC453215-T	HF50ACC453215-T	MPZ2012S101AT000
HF50ACC453215-TD25	HF50ACC453215-TD25	MPZ2012S101ATD25
HF50ACC575018-T	HF50ACC575018-T	MPZ2012S221AT000
HF50ACC575032-T	HF50ACC575032-T	MPZ2012S331AT000
HF50ACC635050-T	HF50ACC635050-T	MPZ2012S601AT000
CB30-0805	HF70ACB201209-T	MMZ1608R150ATA00
CB30-0805-SCI	HF70ACB201209-T	MMZ1608R150ATA00
HF70ACB201209-T	HF70ACB201209-T	MMZ1608R150ATA00
HF70ACB201209-TD25	HF70ACB201209-TD25	MMZ1608R150ATD25

Accept

Company

Department

Name

