



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001049I

DATE: 31-Jan-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1746P-70IND+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	DS1810-5+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	DS21352L+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	DS21Q50L+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	DS9106L-GN0+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX11290LABS#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX1143BCAP+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX1143BCAP+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14651ETA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14651ETA+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14676IEWO+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14676IEWO+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14743EVKIT#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX14743EWC+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14743EWC+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14745CEWX+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14745CEWX+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14745DEWX+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX14745DEWX+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX15021EVKIT+	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX15038EVKIT+	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX159ACPA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX16932EVKIT#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX16970AGTEB/V+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX16970AGTEB/V+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX17048X003+T10	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 03-Mar-2022

Discontinuance	MAX170CEWE+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX170CEWE+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX17140AETL+CGH	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX17140AETL+TCGH	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX1947ETA25+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX1947ETA25+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX20013ATGA/V+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX20013ATGA/V+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX20071EVKIT#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX267AENG+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX2680EVKIT#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX31850NATB+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX31850NATB+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX3232EEAE+TG1Z	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX3483C/D	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX4474EUA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX4474EUA+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX4575ESA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX4587EUB+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX4587EUB+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5094BAUA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5099EVKIT+	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX5159EEE+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5174AEEE+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5361NEUK+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5361NEUK+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX541BEP A+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5901AAEUT+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX5901AAEUT+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6306UK47D2+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6306UK47D2+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6315US45D3+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6315US45D3+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6356SVUT+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6356SVUT+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6387XS16D3+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 03-Mar-2022

Discontinuance	MAX6387XS16D3+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6718UKSDD3+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6718UKSDD3+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6719UTTZD1+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6719UTTZD1+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6735AKASHD3+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6735AKASHD3+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6757UTLD3+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6757UTLD3+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6856UK16D6+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6856UK16D6+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6864UK16D1S+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6864UK16D1S+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6879ETE+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX6879ETE+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX7234BFIQH+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX7234BFIQH+D	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX815KEPA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX816CPA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX824ZEXK+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX824ZEXK+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8511ETA31+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8511ETA31+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8511EXK35+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8511EXK35+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8517EVKIT+	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAX86160AEFN+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX86160AEFN+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8636ETA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8636ETA+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8840ELT15+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX8840ELT15+T	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX9042BESA+	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
Discontinuance	MAX9119LABS#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	MAXREFDES60#	N/A	31-Jan-2022	02-Aug-2023	EVKIT is No Longer Supported
Discontinuance	VT1185MFP	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 03-Mar-2022

Discontinuance	VT239WFQ-ADJ	N/A	31-Jan-2022	02-Aug-2023	Part can no longer be manufactured
----------------	--------------	-----	-------------	-------------	------------------------------------