

---

---

**Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors**

---

---

DATE: February 4th, 2022

RE: Discontinuation of Common Mode Choke Coils

REF NO.: UTY-DN22-02D

TAIYO YUDEN (U.S.A.) Inc. hereby gives notice that the following part numbers are to be discontinued **2/4/2022** for all TAIYO YUDEN (U.S.A) Inc. distributors. Please note that any last time buys must be made on or before **5/4/2022**, with a last time ship date of **2/4/2023**. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

| Discontinued Part Numbers |
|---------------------------|
| BU05MC01T                 |
| BU05MC08T                 |
| TLF9UBH302WK1             |
| TLF9UB302WK1              |
| TLF9UBH802WK1             |
| TLF9UB802WK1              |
| TLF9UBH203WK1             |
| TLF9UB203WK1              |
| TLH10UA9012R0             |
| TLH10UA1121R8             |
| TLH10UA1521R6             |
| TLH10UA2121R4             |
| TLH10UA2821R2             |
| TLH10UA4321R0             |
| TLH10UA6220R8             |
| TLH10UA8720R7             |
| TLH10UA9920R6             |
| TLH10UA1430R5             |
| TLH10UB7012R0             |
| TLH10UB1121R7             |
| TLH10UB1421R4             |
| TLH10UB2321R2             |
| TLH10UB3521R0             |
| TLH10UB4420R8             |
| TLH10UB8720R7             |
| TLH10UB9720R6             |
| TLH10UB1130R5             |
| TLF9UA102W0R8K1           |
| TLF9UA202WR54K1           |
| TLF9UA302WR42K1           |
| TLF9UA502WR32K1           |
| TLF9UA802WR25K1           |
| TLF9UA103WR23K1           |
| TLF9UAH102W0R8K1          |
| TLF9UAH202WR54K1          |
| TLF9UAH302WR42K1          |
| TLF9UAH502WR32K1          |
| TLF9UAH802WR25K1          |
| TLF9UAH103WR23K1          |

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the TAIYO YUDEN sales office responsible for sales in your country for details on this notice.