

230V~

50/60Hz
3p=6h
4p+5p=9h

400V~

50/60Hz
3p=9h
4p+5p=6h

Cat.No.

Cat.No.

Amp.	Poles	pack-unit
16	3	10
16	4	10
16	5	10
32	3	10
32	4	10
32	5	10

013-6x

023-6x

014-6x
015-6x

024-6x
025-6x

new!



023-6x

Amp.	Poles	pack-unit
16	3	10
16	4	10
16	5	10
32	3	10
32	4	10
32	5	10

013-6TTx

023-6TTx

014-6TTx
015-6TTx

024-6TTx
025-6TTx

new!

TURBO TWIS
click



023-6TTx

Amp.	Poles	pack-unit
63	3	2
63	4	2
63	5	2
125	3	2
125	4	2
125	5	2

033-6xs

043-6xs

034-6xs
035-6xs

044-6xs
045-6xs



035-6xs

Amp.	Poles	pack-unit
with flange 70 x 70		
16	3	10
16	4	10
16	5	10
32	3	10
32	4	10
32	5	10

613-6x

623-6x

614-6x
615-6x

624-6x
625-6x



615-6x

Amp.	Poles	pack-unit
with flange 70 x 70		
16	3	10
16	5	10
32	4	10
32	5	10

613-6TTx

615-6TTx

624-6TTx
625-6TTx

TURBO TWIS
click



615-6TTx

Minimum order quantity: 100 pcs

