



5245 Hellyer Avenue
San Jose, CA 95138
U.S.A.
(408) 414-9200

Control No. PDN-22201

May 30, 2022

PRODUCT DISCONTINUATION NOTICE

TYPE OF CHANGE: ☐ Design ☐ Manufacturing ☒ Other: Obsolescence

Product discontinuation signifies the final stage of the product life cycle. It is Power Integrations' policy to provide sufficient notice to customers to allow re-design with replacement parts and/or place final orders. All such orders will be non-cancellable and non-returnable. Please contact your local Power Integrations sales office to arrange final orders for the affected product(s).

DESCRIPTION:

Manufacturing of products listed in the table below will be discontinued.

REASON FOR DISCONTINUANCE:

These products are at the end of life, and there are other more suitable products available for the intended applications.

ALTERNATE PART:

There are no pin-out compatible replacements for the products listed in Table 1. However, LYTSwitch-6 products (see Table 2) are a recommended alternative.

LYTSwitch-6 products provide the same function but are in a different package. Please contact your local PI sales office for samples and assistance in migrating to the LYTSwitch-6 products.

Table 1: Affected Ordering Part Number

Product Family	Ordering Part Number	Package
LYTSwitch-4	LYT4211E, LYT4211E2, LYT4212E, LYT4212E2, LYT4213E, LYT4213E2, LYT4214E, LYT4214E2, LYT4215E, LYT4215E2, LYT4216E, LYT4216E2, LYT4217E, LYT4217E2, LYT4218E, LYT4218E2, LYT4221E, LYT4221E3, LYT4222E, LYT4222E3, LYT4223E, LYT4223E3, LYT4224E, LYT4224E3, LYT4225E, LYT4225E3, LYT4226E, LYT4226E3, LYT4227E, LYT4227E3, LYT4228E, LYT4228E3, LYT4311E, LYT4311E2, LYT4312E, LYT4312E2, LYT4313E, LYT4313E2, LYT4314E, LYT4314E2, LYT4315E, LYT4315E2, LYT4316E, LYT4316E2, LYT4317E, LYT4317E2, LYT4318E, LYT4318E2, LYT4321E, LYT4321E3, LYT4321E4, LYT4322E, LYT4322E3, LYT4323E, LYT4323E3, LYT4324E, LYT4324E3, LYT4325E, LYT4325E3, LYT4326E, LYT4326E3, LYT4327E, LYT4327E3, LYT4328E, LYT4328E3	eSIP-7C

CONFIDENTIAL

The information in this report contains confidential and proprietary information of Power Integrations and its manufacturing partners. By receiving this report, the customer agrees to use this information for the sole purpose of addressing the issues reviewed in this report and to keep the contents confidential. If it becomes necessary for the customer to disclose this information to a third party, a non-disclosure agreement, which provides reasonable and customary protection for the disclosed information, must be executed.



5245 Hellyer Avenue
San Jose, CA 95138
U.S.A.
(408) 414-9200

Control No. PDN-22201

May 30, 2022

Table 2: Recommended Alternative Ordering Part Number

Product Family	Part Numbers	Package
LYTSwitch-6	LYT6063C, LYT6073C, LYT6065C, LYT6075C, LYT6067C, LYT6077C, LYT6068C, LYT6078C, LYT6079C, LYT6070C	InSOP-24D

DISCONTINUATION SCHEDULE:

Our primary goal is to ensure that our customers experience minimal impact through the end-of-life transition for the above-mentioned products. In order to accommodate our customers' needs in the best way possible, Power Integrations can assemble a year of inventory if required. Please contact your local PI sales office if a year of inventory is required.

The last time buy schedule is as follows:

LAST ORDER DEADLINE: May 30, 2023

FINAL SHIPMENT DATE: May 30, 2024

CONFIDENTIAL

The information in this report contains confidential and proprietary information of Power Integrations and its manufacturing partners. By receiving this report, the customer agrees to use this information for the sole purpose of addressing the issues reviewed in this report and to keep the contents confidential. If it becomes necessary for the customer to disclose this information to a third party, a non-disclosure agreement, which provides reasonable and customary protection for the disclosed information, must be executed.