



15-Jul-2022

PCN #: P-22-023050

Subject : AMP SUPERSEAL 1.5 SRS. 2 POSITIONS TAB ASS'Y

Description of Change : Dear Customer, we hereby inform you about a supplier base extension (implementation of recompond resin/material) for the male housing of the mentioned part numbers, which are under the design responsibility of TE Connectivity.

In case of further questions and detailed information, we kindly ask you to get in touch with your sales representative first to achieve a common understanding.

Reason : Part status change. The supplier base extension is needed to protect our customers and TE Connectivity from material shortages and ensure deliveries.

New resin/material introduced is a recompond resin (PA66-GF30), whose industrial grade quality is under TE control.

The TE Connectivity choice is also consistent with the efforts for reducing the CO2 content of our products and build a sustainable future.

These products with recompond resin have been tested according to the relevant specifications and meet the product specific requirements.

Key Dates :

Contact By Date: 15-Aug-2022

Implementation Date: 15-Aug-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
282104-1	"CN7121-000", "AMP-0-0282104-1", "820P-37062"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.