

Product Name:	569 - D-SUB	
	Solder bucket, Straight and Right angled Version 09-37 Position connector	
Product Manager:	Renish Baby	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Packaging change	
Change Description:	Packaging changed from Honeycomb to Tray with packing quantity change. MOQ, MPQ details are modified, as shown in the Affected parts.xls file.	
Reason for Change:	For improvement of the quality of packaging.	
Affected Parts:	Refer attached sheet1	
Effective Date of Change:	10 August ,2022	Note: PCN22087R1 is revision to previous version PCN22087 dtd July 4th, 2022. Affected parts list updated with additional parts
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	NA	
Qual/Test Data Attached?	NA	
Samples Availability Date:	01 August ,2022	
Available Alternatives?		
Questions?	Contact your local Amphenol Representative, or Product Manager	
	Renish Baby / Product Manager	
	Renish.Baby@fci.com	

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .