



Customer Information Notification

202206023I : PCA9509P Data Sheet Max Vih Change

Note: This notice is NXP Company Proprietary.

Issue Date: Jul 29, 2022 **Effective date:** Jul 30, 2022

Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to [view this notification online](#)

Management summary

Changed PCA9509P max Vih specification to clearly indicate A Port, B Port and Enable pins are over voltage tolerant to 5.5V.

Change Category

- | | | | | |
|--|---|--|---|--|
| <input type="checkbox"/> Wafer Fab Process | <input type="checkbox"/> Assembly Process | <input type="checkbox"/> Product Marking | <input type="checkbox"/> Test Process | <input type="checkbox"/> Design |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Errata |
| <input type="checkbox"/> Wafer Fab Location | <input type="checkbox"/> Assembly Location | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Location | <input checked="" type="checkbox"/> Electrical spec./Test coverage |
| <input type="checkbox"/> Firmware | <input type="checkbox"/> Other | | | |

PCN Overview

Description

Changed PCA9509P max Vih specification to clearly indicate A Port, B Port and Enable pins are over voltage tolerant to 5.5V.

There is no change to device or test coverage.

This is only a clarification to current documentation.

Updated data sheet posted on NXP.com www.nxp.com/docs/en/data-sheet/PCA9509P.pdf

Reason

PCA9509P recommended static characteristics Table 6 max Vih specification for A Port, B Port and Enable are the normal value if pull ups are connected to device supply.

Table 6 max Vih voltage is being changed to clearly show the pins are over voltage tolerant.

Port A from Vcc(A) to 5.5V, Port B from Vcc(B) to 5.5V and Enable from Vcc(B) to 5.5V.

Identification of Affected Products

Product identification does not change

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Data Sheet Revision

A new datasheet will be issued

Disposition of Old Products

Not applicable.

Additional information

Additional documents: [view online](#)

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name	Stephen Blozis
Position	Product Marketing Manager
e-mail address	stephen.blozis@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2022 NXP Semiconductors. All rights reserved.