

Product Name:	569 - D-SUB		
	Solder bucket, Straight and Right angled Version 09-37 Position connector		
Product Manager:	Renish Baby		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	Affected customers		
Type of Change:	Packaging change		
Change Description:	Packaging changed from Honeycomb to Tray with packing quantity change. MOQ, MPQ details are modified, as shown in the Affected parts.xls file.		
Reason for Change:	For improvement of the quality of packaging.		
Affected Parts:	Refer attached sheet1		
Effective Date of Change:	01 August ,2022		
Last Time Buy Date:			
Earliest Disty Return Date:			
Last Time Shipment Date			
Datasheet Attached?	NA		
Qual/Test Data Attached?	NA		
Samples Availability Date:	01 August ,2022		
Available Alternatives?			
Questions?	Contact your local Amphenol Representative, or Product Manager		
	Renish Baby / Product Manager		
	Renish.Baby@fci.com		

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .