



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M001080I

DATE: 29-Aug-2022

## PRODUCT DISCONTINUANCE NOTICE

| Notice Type    | Maxim Part Number  | Recommended Replacement | Last Order Date | Last Delivery Date | Reason                             |
|----------------|--------------------|-------------------------|-----------------|--------------------|------------------------------------|
| Discontinuance | DS1088LU-27+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | DS1135LU-12+       | DS1135LZ-12+            | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | DS1135U-8+         | DS1135Z-8+              | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | DS2401AX1-109-61+T | DS2401P+T&R             | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX11802EWC+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX11802EWC+T      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX1188BEUP+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX1243BEPA+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX1264BCEG+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX1292ACEG+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX1292ACEG+T      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX14629EETJ+      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX14629EETJ+T     | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX14690DEWX+      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX14690DEWX+T     | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX14885EETL+      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX14885EETL+T     | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX157BCPA+        | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16037PLA29+     | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16037PLA29+T    | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16133LFM+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16133LFM+T      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16133LFM/V+     | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16133LFM/V+T    | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16508GGN+       | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |
| Discontinuance | MAX16508GGN+T      | N/A                     | 29-Aug-2022     | 28-Feb-2024        | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2022

|                |                   |     |             |             |                                    |
|----------------|-------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX16545GPF+      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX16545GPF+T     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX165ACPN+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX17245ETERA+    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX17245ETERA+T   | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX17499AAUB+     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX17499AAUB+T    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX17605EVKIT#    | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX19506EVKIT#    | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX20070EVKIT#    | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX2472EVKIT      | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX2609EVKIT      | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX317CPA+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX32566-LNJ+     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX32566-LNS+     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX32566-LNS+T    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX355EPE+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4511CPE+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4529ESA+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4529ESA+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4592CUE+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4592CUE+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4613EEE+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4613EEE+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4748EUD+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX4748EUD+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5172AEEE+      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5172AEEE+T     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5362NEUK+      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5362NEUK+T     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5386MEVMINIQU+ | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX542CCPD+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5850EVKIT#     | N/A | 29-Aug-2022 | 28-Feb-2024 | EVKIT is No Longer Supported       |
| Discontinuance | MAX5850EXE+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5850EXE+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX5863ETM+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2022

|                |                    |     |             |             |                                    |
|----------------|--------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX5880PUXF+C73    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6050BEUR+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6050BEUR+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6314US26D2+CD7  | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6384XS46D3+     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6384XS46D3+T    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6423US46+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6423US46+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6457UKD0B+C3G   | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6727KAVHD1+     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6727KAVHD1+T    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6791TPSD2+      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6791TPSD2+T     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6805US44D3+     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6805US44D3+T    | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6811SEUS+C74356 | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6834GXRD0+      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6834GXRD0+T     | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX6977APE+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX739CPD+         | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX774CPA+         | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX793SEPE+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX794CPE+         | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX800MCPE+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX8704EUB+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX8873REUK+       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX8873REUK+T      | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX953EUA+         | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX954EUA+         | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX954EUA+T        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MAX96705GTJ/V+TG5H | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MX7524JP+          | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MX7524JP+T         | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MX7547KCWG+        | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | MX7547KCWG+T       | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
| Discontinuance | VT1196SFQ          | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2022

|                |               |     |             |             |                                    |
|----------------|---------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | VT239WFCX-ADJ | N/A | 29-Aug-2022 | 28-Feb-2024 | Part can no longer be manufactured |
|----------------|---------------|-----|-------------|-------------|------------------------------------|