

Product Change Notice

Issue Date: 2-September-2022

Change Description:

Introduction of new alternate manufacturing site

Parts Affected:

| | | | |
|-----------------|-----------------|-----------------|-----------------|
| ASCB-JTC2-0A208 | ASMB-KTC2-0B406 | QSCB-UTC2-ZA21F | Q1MB-TTF2-ZB20B |
| ASCB-JTC2-0A308 | ASMB-KTF0-0A306 | QSMB-UTF0-0D22B | QSCB-TTF8-0K1AB |
| ASCB-RTC2-0A207 | Q1MB-KTF0-ZA306 | QSMB-UTF2-0E22B | QSCB-TTF8-0M10B |
| ASCB-RTCC-0A207 | ASCB-UTC2-0A30B | Q2MB-UTF0-ZD20B | QSMB-TTF0-ZA20B |
| ASCB-RTF2-0A207 | ASMB-UTF0-0D20B | QSCB-UTF8-ZB20B | QSMB-TTF2-0B20B |
| QSCB-RTF2-ZA207 | ASMB-UTF2-0E20B | ASMB-TTF0-0A20B | ASCB-NTC2-0A307 |
| ASCB-RTF2-0A307 | Q1MB-UTF0-ZD20B | ASMB-TTF2-0B20B | ASCB-HTC2-0A309 |
| ASMB-KTC0-0A406 | Q9MB-UTF2-ZE20B | | |

Description and Extent of Change:

The new alternate manufacturing site has undergone Broadcom's qualification process and is deemed suitable as alternate site.

Reasons for Change:

Assurance of supply.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No change in fit, form and function as per datasheet.

Effective Date of Change:

Broadcom may ship products manufactured from both sites after 90 days from the above issuance date.

Qualification Data:

Qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.