

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Rueiguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com

### **IIoT Product Change Notice**

The change will be applied on the products listed below. If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

## 1. Reason for the Change: Supply chain issues / sourcing

## 2. Affected Products: BB-485TBLED, BB-485SD9TB

#### 3. Impact on Application: No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

#### 4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
BB-485TBLED BB-485SD9TB	WECO 930-T-DS/02 930-T-DS/03	DINKLE EK350V-02P EK350V-03P	Terminal Block	The terminal block color is changing from black to green.	Sourcing and supply chain management.

#### 5. Implementation & Schedule of the Change(s):

Affected Models	ECOM	Estimated	Cut-in	Change
	Number	Effective Date	Implement	Description
BB-485TBLED, BB-485SD9TB	ECOM-193400	January 2023	Running Change	Terminal Block Change

\*Note: Cut-in progress depends on factory production schedule.

# **Contact Windows**

РМ	Brian Foster / <u>brian.foster@advantech.com</u>	
AE	N/A	