

MICRON_Serial NOR Non-Auto Assembly Site Addition of OSE Taiwan

PCN: 34739

Published: 2022-10-14

Revision History:

Revision 1, 2022-11-30: This document supersedes the original PCN #34739, dated 2022-10-14. The address for the additional site (OSE), has been updated to reflect their manufacturing address. The previous address was their Corporate address. It has been corrected in the Description section below.

Type: Manufacturing Site - Change or Addition

Description: Micron is adding assembly site of OSE Taiwan for **Non-Auto** Serial

NOR products QLJS & QLKA SDP 6x8 24b TBGA; QLJS SDP 6x5 & 8x6 8L WPDFN

Site Locations:

Current:

 ATX-SH - ATX Semiconductor Co,Ltd China / Shanghai , No.669, Guoshoujing Road, Zhangjiang Hi-Tech Park, Pudong New Area, Shanghai 201203, P.R.C

Future:

- ATX-SH ATX Semiconductor Co,Ltd China / Shanghai , No.669, Guoshoujing Road, Zhangjiang Hi-Tech Park, Pudong New Area, Shanghai 201203, P.R.C
- **(OSE)** Semiconductor Group Manufacturing, No. 80, Jing 3rd Rd., Nanzih Dist., Kaohsiung 811, Taiwan (R.O.C.)

Samples and Qual Report Availability Dates:

Product Samples Qual Data Product Ship
Available Available Date

	QLKA TBGA SDP 6x8 24b		2022-10-21	2022-10-28	2023-01-19
	QLJS WPDFN SDP 6X5 8L		2022-11-19	2022-11-26	2023-02-17
	QLJS WPDFN SDP 8X6 8L		2022-11-23	2022-11-30	2023-02-21
	QLJS TBGA SDP 6x8 24b		2022-11-26	2022-12-03	2023-02-24
Reason:	Supply Flexibility/Security				
Product Affected:	NOR non-Auto, 1. QLJS/QLKA TBGA SDP 6x8 24b, 2. QLJS WPDFN SDP 6x5 & 8x6 8L				
Affected Micron Part Number COMPONENT		Recommended Replacement		Customer Part Number	
MT25QL256ABA1EW9-0SIT				3530749, MICMT25QL256ABA1!B, MICMT25QL256ABA1!C, MICMT25QL256ABA1>>, MT25QL256ABA1EW9-0SIT TR	
MT25QL256ABA8E12-1SIT				83AH2709, 3530748, MICMT25QL256ABA8!C, MICMT25QL256ABA8!F, MICMT25QL256ABA8>>, MT25QL256ABA8E12-1SIT/FLE)	
MT25QU256ABA1EW7-0SIT				80AH7560, 3577553, MICMT25QU256ABA1!A, MICMT25QU256ABA1!E, MICMT25QU256ABA1E>, MT25QU256ABA1EW7-0SIT TR	
MT25QU256ABA1I	EW9-0SIT			4050798, MICMT25QU256ABA1!B, MICMT25QU256ABA1>>	
MT25QU256ABA8I	E12-1SIT			MICMT25QU25 MICMT25QU25 MT25QU256AI	
MT35XU512ABA10	612-0SIT			MICMT35XU51	.2ABA1G>
	*Mat	erials that have be	een ordered are ir	n bold .	
Method of Identification:	Master shipping container label will indicate country of origin from China to Taiwan.				
Micron Sites Affected:	Subcontractor				
Qualification Plan:					
Sample Available:	2022-10-21				
•					

Qual Data Available: 2022-12-03

Product Ship Date: 2023-01-12

DISCLAIMER: INFORMATION IN THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS WITHOUT WARRANTIES OF ANY KIND. INFORMATION REGARDING PRODUCTS, INCLUDING STATEMENTS REGARDING PRODUCT FEATURES, AVAILABILITY, FUNCTIONALITY, OR COMPATIBILITY, ARE PROVIDED FOR INFORMATIONAL PURPOSES ONLY AND DO NOT MODIFY THE WARRANTY, IF ANY, APPLICABLE TO ANY PRODUCT, AND MICRON DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY RELATING TO SALE AND/OR USE OF PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT.

NOTE: Per JEDEC Standard J-STD-046 Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.