



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001085A

DATE: 04-Jan-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX17515ELI+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAX17515ELI+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17502ALI#	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17502ALI#T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17503ALJ+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17503ALJ+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17504ALJ+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17504ALJ+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17505ALJ+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17505ALJ+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17514ALI+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17514ALI+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17515ALI+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17515ALI+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17516ALI+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17516ALI+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17543ALJ+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17543ALJ+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17544ALJ+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17544ALJ+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17545ALJ+	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17545ALJ+T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17574ALC#	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17574ALC#T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17575ALI#	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17575ALI#T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Feb-2023

Discontinuance	MAXM17761ALI#	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured
Discontinuance	MAXM17761ALI#T	N/A	04-Jul-2023	14-Jun-2024	Part can no longer be manufactured