



Expertise Applied | Answers Delivered

PRODUCT CHANGE NOTICE

Issue Date: November 8th, 2022

Dear Valued Customer,

This notice is to inform about a change in one of the finished good(s) you have purchased from Littelfuse.

Description of the Change:

- Littelfuse will move to a new supplier of several components used in the attached Littelfuse finished good(s).

Reason for The Change:

- We will be moving to consolidate suppliers as current supplier is no longer capable to sustain commercial terms.

Effective Date of the Change:

- This will be a running change starting in Q1 2023 and to be completed by Q4 2023.

What You Need to Do:

- No action is required in your behalf. There is no change in product fit, form or function.

If you have any questions, please feel free to contact your Littelfuse Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Marian Fernanda Corrales

Associate Product Manager
Littelfuse Commercial Vehicle Products

Affected Part(s)	Affected Part(s)	Affected Part(s)	Affected Part(s)
02980900S	02981002ZXT	02981039ZXT	0498900.TXN
02980900TXN	02981003ZXT	02982002ZXT	298907-010
02980900Z	02981005ZXT	02982011ZXT	298907-030
02981001ZXT	02981012ZXT	02983006ZXT	02980900S
02981002ZXT	02981014ZXT	CFLEC001Z-01	02980900TXN
02981003ZXT	02981024ZXT	CFLEC003Z-01	02980900Z
02981005ZXT	02981027ZXT	CFLEC003Z-02	02981001ZXT
02981012ZXT	02981030ZXT	CFLEC003Z-03	02981002ZXT
02981024ZXT	02981034ZXT	FLEC0002Z-0	02981003ZXT
02981030ZXT	02981035ZXT	FLEC0014Z-0	02981005ZXT
02981034ZXT	02981039ZXT	FLEC0016Z-0	02981012ZXT
02981008ZXT	02982002ZXT	FLEC0016Z-1	02981014ZXT
02981015ZXT	02982011ZXT	FLEC0018Z-0	02981024ZXT
04980900S	02983006ZXT	FLEC0019Z-0	02981027ZXT
04980900ZXT	02981001ZXSS	FLEC0020Z-0	02981030ZXT
04980903-BP	02981008ZXT	FLEC0020Z-1	02981034ZXT
04980903ZXT	02981015ZXT	FLEC0020Z-2	02981035ZXT
04980904ZXT	02981036ZXT	FLEC0021Z-1	02981039ZXT
04980905ZXT	02983001ZXFC	FLEC0021Z-2	02982002ZXT
04980923ZXT	02985003ZXFC	FLEC0022Z-01	02982011ZXT
0498900.TXN	02985004ZXFC	FLEC0023Z-01	02983006ZXT
02980900S	04980900S	FLEC0025Z-01	CFLEC001Z-01
02980900TXN	04980900ZXT	FLEC0026Z-01	CFLEC003Z-01
02980900Z	04980902ZXT	FLEC0027Z-01	CFLEC003Z-02
02981001ZXT	04980903-BP	FLEC3000Z-0	CFLEC003Z-03
02981002ZXT	04980903ZXT	FLEC3000Z-0U	FLEC0002Z-0
02981003ZXT	04980904ZXT	02981001ZXSS	FLEC0004Z-2
02981005ZXT	04980905ZXT	02981002ZXSS	FLEC0004Z-4
02981012ZXT	04980908ZXT	02981008ZXT	FLEC0004Z-7
02981024ZXT	04980913ZXT	02981015ZXT	FLEC0004Z-9
02981030ZXT	04980917ZXT	02981036ZXT	FLEC0010Z-0
02981034ZXT	04980923ZXT	02983001ZXFC	FLEC0014Z-0
02981001ZXSS	0498900.TXN	02985003ZXFC	FLEC0015Z-0
02981008ZXT	298907-010	02985004ZXFC	FLEC0016Z-0
02981015ZXT	298907-030	04980900S	FLEC0016Z-1
04980900S	02981002ZXSS	04980900ZXT	FLEC0017Z-1
04980900ZXT	02980900S	04980902ZXT	FLEC0017Z-10
04980902ZXT	02980900TXN	04980903-BP	FLEC0017Z-11
04980903-BP	02980900Z	04980903ZXT	FLEC0017Z-12
04980903ZXT	02981001ZXT	04980904ZXT	FLEC0017Z-2
04980904ZXT	02981002ZXT	04980905ZXT	FLEC0017Z-3
04980905ZXT	02981003ZXT	04980908ZXT	FLEC0017Z-4

04980923ZXT	02981005ZXT	04980913ZXT	FLEC0017Z-5
0498900.TXN	02981012ZXT	04980917ZXT	FLEC0017Z-6
298907-010	02981014ZXT	04980923ZXT	FLEC0017Z-7
298907-030	02981024ZXT	04981038-BP	FLEC0017Z-8
02980900S	02981027ZXT	04981038HXFC	FLEC0017Z-9
02980900TXN	02981030ZXT	04981038HXFC-A	FLEC0018Z-0
02980900Z	02981034ZXT	04982001ZXFC	FLEC0019Z-0
02981001ZXT	02981035ZXT	04982002ZXFC	FLEC0020Z-0
FLEC0020Z-1	FLEC0027Z-01	65162	75221-18
FLEC0020Z-2	FLEC3000Z-0	67206	75226-01
FLEC0021Z-1	FLEC3000Z-0U	67207	75226-BX
FLEC0021Z-2	LFHCD002Z-01	67234	75921-02
FLEC0022Z-01	LFHCD002Z-02	75226	75921-03
FLEC0023Z-01	LFHCD002Z-03	67234-01	75921-10
FLEC0024Z-0	LFHCD002Z-04	75221-09	
FLEC0025Z-01	LFHCD002Z-05	75221-09-BX	
FLEC0026Z-01	6301	75221-15	