

Eaton

Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

# **Product Change Notice**

PCN#: EE-PCN23006 2/28/2023

### **CLASSIFICATION OF CHANGE:**

FIT

### **DESCRIPTION OF CHANGE:**

Change product label marking. The change eliminates spaces between the markings which point to the negative lead.

V-type
Top View

New Marking

New Marking

FION XXXY

FION XXXY

FION XXXY

FION XXXY

FATO

EATO

Side View

New Marking

FION XXXY

FION XXXY

FATO

EATO

EATO

Side View

#### **REASON FOR CHANGE:**

Improve optical machine readability.

### **EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

There will be no effect on the quality, reliability, or performance. Higher machine read rates in automated systems

## **PARTS AFFECTED:**

KR-5R5H104-R	KR-5R5H474-R	KR-5R5V334P-R
KR-5R5H105-R	KR-5R5V104-R	KR-5R5V334-R
KR-5R5H155-R	KR-5R5V105-R	KR-5R5V474-R
KR-5R5H224-R	KR-5R5V155-R	
KR-5R5H334-R	KR-5R5V224-R	

### TIME SCHEDULE:

Start Shipment Date: 5/28/2023 Last Time Buy Date: N/A Last Time Shipment Date: N/A

**SAMPLE AVAILABILITY: UPON REQUEST** 

**QUALIFICATION DATA: N/A** 

**ISSUED BY:** 

Global Product Manager – Jason Lee

### **CONTACT INFORMATION:**

For questions or comments, please Contact us

F202D-02 PCN Rev 02/28/2017