

## **Product Change Notification**


	<b>3</b>		
Date Issued :	May 12, 2023	PCN Number :	513402
Reason for Change :	Change to Product		
Description of Change :	The recommended PCB layout in the drawing for PN 855437002 has been changed; there is no form/fit/functional impact on the part.		
Reason for Short Notice :	Special Request		
Assessment of Change :	No change to parts - Form/Fit/Function		
Planned Implementation Date :	July 15, 2023		
Sample Availability Date:	May 31, 2023		
Internal Molex Qualification Date :	May 31, 2023		
Last date to request Samples by Custo	omer: June 30, 2023		

No special marking on the product or packaging

Before Picture

Traceability Code Markings / Date :


## ■ Photo of affected product



After Picture

## Overview

■ The recommended PCB layout in the drawing for PN 855437002 has been changed; there is no form/fit/functional impact on the part.



- Product Impact: no impact to fit, form or function
- Part Number Impact: 855437002



You may address inquires regarding this PCN by clicking on the below link mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:513402 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 513402" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com