

Product discontinuation

PD_205_23A **UPDATE** - updated information in **blue type** -

| | |
|-----------------------|------------|
| ■ Last order date: | 2025-06-30 |
| ■ Last delivery date: | 2026-12-31 |

Reason: Product portfolio rationalization

Original: Product Discontinuation N° PD_205_23 dated 2023-07-03

Update: **Update replacement parts for SP000382100 from SP005574087 to SP005574085; SP001580180 from SP005574085 to SP005574087**

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|--------------|-------------|------------------|----------|-----------------------|------------------------|----------------------------|---------------------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| TLE6250G | SP000316311 | TLE6250GXUMA1 | PG-DSO-8 | TLE9350SJ | SP005574082 | TLE9350SJXTMA1 | PG-DSO-8 |
| TLE6250G V33 | SP000382100 | TLE6250GV33XUMA1 | PG-DSO-8 | TLE9350XSJ | SP005574087 | TLE9350XSJXTMA1 | PG-DSO-8 |
| | | | | TLE9350VSJ | SP005574085 | TLE9350VSJXTMA1 | PG-DSO-8 |
| TLE6250G | SP001580180 | TLE6250GXUMA2 | PG-DSO-8 | TLE9350VSJ | SP005574085 | TLE9350VSJXTMA1 | PG-DSO-8 |
| | | | | TLE9350XSJ | SP005574087 | TLE9350XSJXTMA1 | PG-DSO-8 |
| TLE6250C | SP001607488 | TLE6250CX2LA2 | N.A. | | none | | |
| TLE6250C V33 | SP001607492 | TLE6250CV33X2LA2 | N.A. | | none | | |

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.