



Expertise Applied | Answers Delivered

## PRODUCT CHANGE NOTICE

**Issue Date:** March 27<sup>th</sup>, 2023

Dear Valued Customer,

This PCN C0454 notice is to inform you of a supplier change of several items that you have purchased from Littelfuse.

***Description of the Change:***

Due to supplier increases in lead-time and cost which are affecting the supply chain causing shortages in components, Littelfuse will be sourcing a new supplier to ensure business continuity and avoid supply chain disruptions. There will be no change in fit, form or function of the finished good P/Ns.

***Reason for The Change:***

Due a few challenges we have faced with our current supplier, Littelfuse will be moving business to a new supplier.

***Effective Date of the Change:***

Running change starting on November 16, 2023

***What You Need to Do:***

Please, notify your customers who have purchased these P/Ns in the past.

If you have any questions, please feel free to contact your Littelfuse Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

*Renata Cebada*

Associate Product Manager  
Commercial Vehicle Products

| Affected PN | Affected PN | Affected PN  | Affected PN   |
|-------------|-------------|--------------|---------------|
| 11041       | 7786-01     | 880371400-BX | 9106-02       |
| 11041-06    | 7786-03     | 880371401    | 91105         |
| 11041-06-BX | 7786-BX     | 880371401-BX | 91105-BX      |
| 11041-BX    | 7787        | 880371402    | 91109-03      |
| 1108        | 7787-01     | 880371402-BX | 91113         |
| 11178-BX    | 7789-01     | 880371403    | 91113-05      |
| 1160        | 7789-02     | 880371403-BX | 91113-19      |
| 12300       | 7789-02-BX  | 880371404    | 91113-20      |
| 12300-BX    | 7792        | 880371404-BX | 91113-BX      |
| 12301       | 7792-01     | 880371405    | 91115-04      |
| 12301-BX    | 7792-01-BX  | 880371405-BX | 91126         |
| 12310       | 7792-03     | 880371406    | 91126-07      |
| 12310-BX    | 7792-BX     | 880371406-BX | 91126-BX      |
| 12311       | 7803-01     | 880371407    | 9162-03       |
| 12311-BX    | 7804        | 880371407-BX | 91830-03      |
| 1283-325    | 7804-01     | 880371408    | 92102         |
| 1283-325-BX | 83280       | 880371408-BX | 92102-BX      |
| 24024       | 83280-BX    | 880371409    | 92107-03      |
| 24025-03    | 880000030   | 880371409-BX | 92107-03-WBXC |
| 24025-04    | 880000040   | 880371410    | 92107-04      |
| 2484-03     | 880051      | 880371410-BX | 92107-04-BX   |
| 2484-03-BX  | 880051-10   | 880371411    | 92107-06      |
| 2484-06     | 880055      | 880371411-BX | 92107-10      |
| 2484-06-BX  | 880062      | 880371412-BX | 92107-14      |
| 2484-19     | 880062-BP   | 880371413    | 92116         |
| 2484-19-BX  | 880064      | 880371413-BX | 92116-07      |
| 2484-43     | 880064100   | 880371414    | 92116-BX      |
| 2484-52     | 880072B     | 880371414-BX | 92120         |
| 40100       | 880073      | 880371415    | 92120-01      |
| 40100-04    | 880073300   | 880371415-BX | 92126-01      |
| 40100-BX    | 880073301   | 880371416    | 9216          |
| 48525       | 880075      | 880371416-BX | 9216-03       |
| 48525-BX    | 880075S     | 880371417    | 9216-03-BX    |
| 48530       | 880076      | 880371418    | 9216-10       |
| 48530-01    | 880086      | 880371500    | 9216-BX       |
| 48530-BX    | 880088      | 880371500-BX | 9224          |
| 50001       | 880111100   | 880371501    | 9224-12       |
| 50001-BX    | 880154      | 880371501-BX | 9224-26       |
| 50002       | 880159      | 880371502    | 9224-BX       |
| 50002-BX    | 880159100   | 880371502-BX | 9242          |
| 50037       | 880159S     | 880371503    | 9242-01       |
| 50066       | 880160      | 880371503-BX | 9242-01-BX    |

|             |              |              |             |
|-------------|--------------|--------------|-------------|
| 50066-12    | 880175       | 880371504    | 9242-BX     |
| 50066-13    | 880175-0001  | 880371504-BX | 9270-01     |
| 50090-04    | 880175-0002  | 880371505    | 9270-01-BX  |
| 50103       | 880175-1001  | 880371505-BX | 95033       |
| 50106       | 880175S      | 880371506    | 95033-BX    |
| 55017-02    | 880176800    | 880371506-BX | 95070-04    |
| 55021-04    | 880176800A   | 880371507    | 95420       |
| 55021-04-BP | 880176801    | 880371507-BX | 95521-01    |
| 55021-04-BX | 880176801A   | 880371508    | 95521-01-BX |
| 5584-11     | 880208100    | 880371508-BX | 95521-08    |
| 67179       | 880208200    | 880371509    | 95521-B     |
| 68166-07    | 880208300    | 880371509-BX | 95521-B-BX  |
| 68166-08    | 880208400    | 880371510    | 95522-11    |
| 68166-11    | 880208500    | 880371510-BX | 95522-A     |
| 68166-12    | 880208550    | 880371511    | 95524-A     |
| 68166-14    | 880208580    | 880371511-BX | 95524-A-BX  |
| 68166-15    | 880208600    | 880371513    | 95525-A     |
| 68166-16    | 880208650    | 880371513-BX | 95561-01    |
| 68166-19    | 880208680    | 880371514    | 95564       |
| 68166-20    | 880208700    | 880371514-BX | 95591       |
| 71066-05    | 880208750    | 880371515    | 95591-01    |
| 72051-03    | 880208755    | 880371515-BX | 95591-BX    |
| 72051-05    | 880208780    | 880371516    | 95597       |
| 72058-02    | 880208800    | 880371517    | 956-3124    |
| 72062       | 880208850    | 880371600    | 956-3124-BX |
| 72079-01    | 880208855    | 880371600-BX | 956-3127    |
| 72095       | 880208880    | 880371700-BX | 956-3127-BX |
| 72096       | 880217       | 888842000    | 956-3135    |
| 72097       | 880218100    | 888842000A   | 956-3146    |
| 72100       | 880218303    | 888842001    | 956-4107    |
| 72100-BX    | 880301       | 888842001A   | 956-4111    |
| 72101       | 880302       | 888842101A   | 956-4111-BX |
| 72107       | 880308100    | 888842200    | 956-4113    |
| 75502-02    | 880308150    | 889028100    | 956-4124    |
| 75502-04    | 880308200    | 889115401    | 956-4124-BX |
| 75700-01    | 880308250    | 90000-01     | 956-4141    |
| 75708-04    | 880371200    | 90002-01     | 956-4307    |
| 75712-01    | 880371200-BX | 90020        | 956-5124    |
| 75712-04    | 880371201    | 90030-44     | 956-5307    |
| 75712-04-BX | 880371201-BX | 90036-10     | 956-6307    |
| 75717       | 880371202    | 90043        | 956-6310    |
| 75900-14    | 880371202-BX | 90043-06     | 956-9100    |
| 75900-16    | 880371203    | 90043-07     | 956-9100-BX |

|              |              |             |             |
|--------------|--------------|-------------|-------------|
| 75900-22     | 880371207    | 90043-07-BX | 95607-01    |
| 75900-23     | 880371207-BX | 90043-23    | 95612       |
| 75904-01     | 880371208    | 90043-24    | 95612-02    |
| 75904-01-BX  | 880371208-BX | 90043-25    | 95612-BX    |
| 75904-03     | 880371209    | 90043-26    | 95613       |
| 75904-03-BX  | 880371209-BX | 90043-31    | 95613-04    |
| 75904-07     | 880371210    | 90043-33    | 95613-BX    |
| 75904-10     | 880371210-BX | 90043-35    | 95668-02    |
| 75904-11WBXV | 880371211    | 90043-38    | 95669-02    |
| 75904-12     | 880371211-BX | 90043-39    | 95669-03    |
| 75907        | 880371213    | 90043-40    | 95669-04    |
| 75907-BX     | 880371213-BX | 90043-44    | 95689-02    |
| 75908        | 880371214    | 90043-47    | 95690-04    |
| 75908-02     | 880371214-BX | 90043-BX    | 95690-05    |
| 75908-BX     | 880371215    | 90050       | 95690-06    |
| 75909-01     | 880371215-BX | 90050-02    | 95690-07    |
| 75910        | 880371216    | 90060-03    | 95690-09    |
| 75910-01     | 880371216-BX | 90060-05    | 95690-10    |
| 75910-01-BX  | 880371217    | 90060-06    | 95690-10A   |
| 75912        | 880371218    | 90065       | 95695-04    |
| 75912-01     | 880371219    | 90065-01    | 95704       |
| 75912-BX     | 880371220    | 90065-02    | 95704-01    |
| 75914        | 880371300    | 90065-06    | 95704-04    |
| 75915        | 880371300-BX | 90065-07    | 9800        |
| 75920        | 880371301    | 90066-02    | 9802-03     |
| 75920-01     | 880371302    | 90068       | M-121       |
| 75920-02     | 880371302-BX | 90069       | M-121-BP    |
| 75920-03     | 880371303    | 90071-02    | M-284-02    |
| 75920-04     | 880371303-BX | 90071-03    | M-284-02-BX |
| 75920-05     | 880371304    | 90072-01    | M-290-07    |
| 75920-06     | 880371304-BX | 90072-05    | M-482       |
| 75920-10     | 880371305    | 90073-04    | M-482-BP    |
| 75920-12     | 880371305-BX | 90073-05    | M-482-BX    |
| 75920-BP     | 880371306    | 90073-06    | M-485       |
| 75920-BX     | 880371306-BX | 90073-07    | M-485-01    |
| 75921-02     | 880371307    | 90074       | M-485-BP    |
| 75921-03     | 880371307-BX | 9044        | M-524       |
| 75921-10     | 880371308    | 9044-BX     | M-530       |
| 7784         | 880371308-BX | 9096-02     | M-606       |
| 7784-BX      | 880371311    | 9096-02-BX  | M-606-BP    |
| 7785-01      | 880371311-BX | 91042       | M-606-BX    |
| 7785-01-BX   | 880371312    | 91045-05    | M-608       |
| 7785-02      | 880371313    | 91045-06    | M-608-07    |

|            |           |               |             |
|------------|-----------|---------------|-------------|
| 7785-02-BX | 880371314 | 91045-07      | M-608-12    |
| 7786       | 880371400 | 91045-08-WBXC | M-608-BP    |
| M-608-BX   | M-639-02  | M-750-BP      | M-914-01    |
| M-639      | M-639-BX  | M-754         | M-914-01-BX |
| M-639-01   | M-750     | M-754-BP      | M-91808     |