



To All ebm-papst Distributors,

Product Change / Discontinuation Notice

In an ongoing effort to keep our product offering streamlined with the latest component technology, we are discontinuing select products. Attached is a list of the part numbers along with their recommended replacements (where applicable).

- Last time buys for the discontinued items can be made through March 31, 2015

For any products that do not have a recommended replacement, please work with your local ebm-papst sales representative, Regional Distribution Manager, or me to find an alternate solution. We can also help your sales people get the alternative ebm-papst products on the "bill of material."

Supporting Documentation Attached

- **1-2015 Product Disc – Repl**
List of discontinued products with recommended replacements, where applicable (includes comparison datasheets)
- **NPT 1-2015 Repl Products**
Product Template for recommended replacements
- **Datasheets**
3300N
6314H
6318H
Speed Signal_2
- **Product Images**

3300N
6300H

Please let me know if you have questions, or if you need any further information.

Best Regards,

Mike Rota

Director – Distributor Sales NAR
Mobile: 201-410-1891

ebm-papst Inc.

100 Hyde Rd.
Farmington, CT 06034
phone: 860-674-1515
fax: 860-674-8536
email: sales@us.ebmpapst.com
web: www.ebmpapst.us



our commitment to eco-friendly production