onsemi

Product Discontinuance Document #:PD25141X6 Issue Date:30 Aug 2023

Title of Change:	Update to PD25141 series - Reactivation of previously discontinued parts			
Last Time Buy Date:	NA			
Last Ship Date:	NA			
Contact information:	Contact your local onsemi Sales Office or <u>PCN.Support@onsemi.com</u>			
Description and Purpose	:			
onsemi wishes to inform our customers of our intent to reactivate of the device listed below, which were previously discontinued in PD25141 series.				
The parts shall be considered active.				
For questions or concerns regarding this notification, please contact your local sales office or customer service representative.				
Additional contacts are:				
Americas:	E	urope:		
Tom Siegel (tom.siegel@onsemi.com)		Andrej Tomasik (andrej.tomasik@onsemi.com)		
🖀 +1 765 868 50	22	🖀 +421 33790 2229		
USA		Slovakia		
Japan:	A	sia Pacific:		
Isao Usuki (isao.us	suki@onsemi.com)	Stephen Ng (stephen.ng@onsemi.com)		
🖀 +81 3 6880 17	71	2 +852 2689 0209		
Japan		China		

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u>PCN Customized Portal</u>.

Part Number	Replacement part	Supplier
NC7SB3157P6X	#NONE	#NA
NC7SB3157L6X	#NONE	#NA
FSA4159P6X	#NONE	#NA
FSA4157AP6X	#NONE	#NA
FPF1006	#NONE	#NA
FAN4274IMU8X	#NONE	#NA
FAN4174IS5X	#NONE	#NA
FAN48630BUC31JX	#NONE	#NA