



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001099

DATE: 11-Oct-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX32000CCB+	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	MAX32000CCB+T	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	MAX32670GTLCV+	N/A	11-Oct-2023	11-Oct-2023	The part was not released
Discontinuance	MAX32670GTLCV+T	N/A	11-Oct-2023	11-Oct-2023	The part was not released
Discontinuance	PHY1040-01QT-BR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1040-01QT-RR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1070-01QD-BR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1070-01QD-RR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1076-01QD-RR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078-01QT-BR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078-01QT-RR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078QT-BR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078QT-RR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY2078QT-RR	N/A	19-Feb-2024	03-Apr-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 11-Nov-2023