46410 fremont boulevard fremont, ca 94538 usa 925.583.8400 **bridgelux.com**



Oct 11th, 2023

To: Bridgelux Customers and Authorized Distributors

Re: End of Life Notice (EOL) for Vesta Flex Casambi module

Ref: BL-EOL-10112023

Bridgelux is announcing the discontinuation of its Vesta Flex Casambi wireless module. Replacement option is not available due to the discontinuity of Casambi CBM-002 wireless module.

Description of Change	Termination of Vesta Flex Casambi wireless module
	Change to Brigelux Dual Channel Drivers (DALI / 0-10V) and Casambi CBU-A2D Modules
Last order date of obsolesced part	Not applicable. Part cannot be ordered anymore
Last ship date of obsolesced part	Not applicable. Part will not be shipped anymore

Affected part numbers:

EOL Part Number	Recommended Replacement Part Numbers
BXCS-12C-N2P-01-A	Casambi CBU-A2D wireless module + Bridgelux Dual Chanel Drivers (DALI / 0-10V):
	US drivers: Vesta Fusion (0-10V)
	EU Driver: Vesta-D (DALI)

Please acknowledge receipt of this notification and provide feedback along with any additional requests to your Bridgelux Account Manager or Quality Manager no later than Oct 31st, 2023.

Sincerely, Your Bridgelux Product Management Team