UPtoDATE



December 15, 2023

PTN

Stop of production of ferrite cores with MnZn material T46

As the material is discontinued, the following EPCOS ferrite cores produced from SIFERRIT material T46 (MnZn) are being withdrawn without substitute types and the production will be stopped. For alternative parts please contact your regional sales contact.

Affected products

Ordering code	Ordering code	Ordering code
B66305F0000X146	B64290P0751X046	B66307H1000X146
B65513S4201X146	B64290P0692X046	B64290L0755X046
B66307F0000X146	B64290S8038X023	B64290L0761X046
B66379F0000X146	B64290L0038X046	B64290S7740X002
B62152S0027X006	B64290A0681X046	B64290P0687X046
B64290P0036X046	B64290P0681X046	B65513S4101X146
B64290P0037X046	B64290L0062X046	B66315F0000X146
B64290S7037X021	B64290L0742X046	B64290L0783X046
B64290P0723X046	B66311F0000X146	B62152A0008X046
B64290P0739X046	B66307S1001X146	B64290S7779X002

Deadline for last orders: March 28, 2024 Last shipments by: June 28, 2024

Contact Philipp Laurer, MAG TF F PM, Munich

Customers are asked to address inquiries directly to their sales contacts.

www.tdk-electronics.tdk.com

MAG