



22-Nov-2024

PCN #: P-24-027215

Subject : 4P PLUG HOUSING

Description of Change : Dear customer, we hereby inform you about the mold replacement project for the production of housing connectors used to assembly the PN's 282088-1 and 282088-3 connector.

Reason for Change: Document clarification. Dear customer, as result of our continuous strive for improving our processes we hereby inform you about the mold replacement project for the production of housing connectors used to assembly the PN 282088-1 and 282088-3 connector in brazilian plant. The production will be executed by following a strict procedure which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. PCN Create Please after receiving this notification, PPAP and samples must be requested by ePPAP System in 14 days. In case of you do not request in ePPAP, TE will understand and consider that this change was accepted.

Key Dates :

Contact By Date:09-Dec-2025

Implementation Date:09-Dec-2025

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
282088-1	31AMP282088-1-M		
282088-3			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by Accuris based on content provided by TE Connectivity.

