



## Product Change Notification: CENO-04ERJY094

---

### Date:

12-Dec-2024

### Product Category:

Driver / Interface ICs

### Notification Subject:

eSign # EOL0000380: End of Life of HV5523K7-G and HV5623K7-G catalog part numbers (CPN).

### Affected CPNs:

**CENO-04ERJY094\_Affected\_CPN\_12122024.pdf**

**CENO-04ERJY094\_Affected\_CPN\_12122024.csv**

**PCN Status:** End of Life (EOL) Notification

### Microchip Parts Affected:

Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**EOL Description:** The HV5523K7-G and HV5623K7-G catalog part numbers (CPN) will be moving to End of Life(EOL) status effective today. These catalog part numbers will no longer be offered after December 12, 2024. Please review the attached parts affected list below for the details about replacement parts if applicable.

**Note:** If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

**Reason for EOL:** No longer have manufacturing support for the CPN listed in the attachment.

**Estimated Effective Dates:** 12-12-2024

**Revision History:** December 12, 2024: Issued EOL notification.

**Note:** The change described in this PCN does not alter Microchip's current regulatory compliance

regarding the material content of the applicable product.

## **Attachments:**

**PCN\_CENO-04ERJY094\_Recommended Replacements.xlsx**

**PCN\_CENO-04ERJY094\_Recommended Replacements.pdf**

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

HV5523K7-G

HV5623K7-G

PCN_CENO-04ERJY094		
EOL Catalog Part Number (CPN)	Recommended Replacement	Notes for Recommended Replacement
HV5523K7-G	HV5524K7-G	Pin-to-pin replacement. Same silicon, same package, different assembly wire bond <a href="#">Contact Your Local Sales Office</a>
HV5623K7-G	HV5624K7-G	