

End Of Life Notice
Notification – PLC25003A
[4 March 2025]

To: Our Valued Customers

Overview: The purpose of notice PLC25003A is to correct a date error on the 1st page of notice PLC25003. The 4-MAR-25 date should have been 4-Mar-26 (see red text for update below). No other changes were made to the original notice.

Affected Products: Attached is a list of products affected by this notification. Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:

Standard Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	4-Sep-25
Last Shipment (LTS)	4-Mar-26
Custom / Proprietary Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	4-Mar-26
Last Shipment (LTS)	4-Sep-26

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Renesas Electronics America Inc. will attempt to honor all such purchase orders and scheduled delivery dates but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Any order resulting from this notice shall be governed by Renesas's General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative or Central Applications @ 1-888-468-3774 for any questions or comments.

Thank you for your attention.

Sincerely,
Renesas Electronics

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re- Design Part Number	Reason
ISL6256AHAZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6256AHAZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6258AHRTZ-R5394	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6258AHRTZ-R5394A	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6258AHRTZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6258AHRTZ-TS2378A	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6258AHRTZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6259AHRTZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL88732HRTZ-R5601	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL88732HRTZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9519HRTZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9519HRTZ-TS2720	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9519IRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9519IRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL94208IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL94208IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97519AIUZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97519AIUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97519AIUZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634ART26Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634ART26Z-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT14Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT14Z-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT18Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT18Z-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT18Z-TS2568	3/4/2025	3/4/2026	9/4/2026	None	Manufacturing Discontinuation
ISL97634IRT26Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT26Z-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97634IRT26Z-TS2568	3/4/2025	3/4/2026	9/4/2026	None	Manufacturing Discontinuation
ISL97656AIRTZ-TS2378	3/4/2025	3/4/2026	9/4/2026	None	Manufacturing Discontinuation
ISL97656IRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97656IRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97656IRTZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97519AIUZEVALZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL97656IRTZEVALZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95808BW	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883BHRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95835IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95835IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95837IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95837IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95831CHRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95831CIRTZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL95831HRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95831HRTZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL95832IRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6617AFRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6617AFRZ-TS2709	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AHRUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AHRUZ-TS5749	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AHRUZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AIRUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AIRUZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL95870BHRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870BHRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870BHRZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL95870BIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870BIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870BIRZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL95870HRUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870HRUZ-TS5720	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870IRUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883CHRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883CHRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883CIRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883CIRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62882HRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62882IRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883IRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6227CAZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6227IAZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62386HRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62386HRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62392HRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re- Design Part Number	Reason
ISL62383HRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62870HRUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62871HRUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6334DCRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6334DCRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6334DIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6334DIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6615IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6265AHRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6265AHRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6341ACRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6341AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6341CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6341IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228HRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228HRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228IRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228IRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262ACRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262ACRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6261ACRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6261AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6236AIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6327IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8702IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8702IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6545CBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6545IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6545IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6596CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6596IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6609ACBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6609AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6269BCRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6269BCRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6269BIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL88550AIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL88550AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6612ACBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208BCRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208CBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208CBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208CBZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL6208CRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6261AIRZ-TR5392	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262ACRZ-TR5338C	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262ACRZ-TR5350	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6267HRZR5482	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6267HRZR5489	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6267HRZ-TR5482	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6267HRZ-TR5489	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95808BWR6018	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95808HRZ-TR5872	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6208BCRZ-TS2490	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262ACRZ-TS2704	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262AIRZ-TS2704	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6262CRZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62882CHRTZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62882HRTZ-TR5390	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883BHRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62883IRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95831CIRTZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95831HRTZ-TR5535	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95832HRTZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6227CAZ-TR5151	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6227IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228HRTZ-TR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228HRTZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6228HRTZ-TS2705	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re- Design Part Number	Reason
ISL6236IRZA-TR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6236IRZA-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6236IRZA-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62383HRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62383HRTZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL62383HRTZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6263CHRZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6269ACRZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6269BCRZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9563BHRZ-TR5400	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AHRUZ-TR5627	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870AHRUZ-TR5753	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870HRUZ-TR5758	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL95870HRUZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6312CRZ-TR5350	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6314CRZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL99135AFRZ-TR5860	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420AEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420AEVAL3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420AIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420AIRZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420AIRZ-TKS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420AIRZ-TKS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL6420BEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420BEVAL2Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420BIAZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420BIAZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420BIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420BIRZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6420BIRZ-TKR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105ACRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105ACRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105AEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105AIBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105AIBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105AIBZ-TR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105AIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8105IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8112EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8112IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8112IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8118CRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8118CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8118EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8118IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8118IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8118IRZ-TS2800	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120CRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120EVAL3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120EVAL4Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120IRZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120IRZ-TR5568	3/4/2025	9/4/2025	9/4/2026	None	Manufacturing Discontinuation
ISL8120IRZ-TR5779	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8120IRZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL8120IRZR5568	3/4/2025	9/4/2025	9/4/2026	None	Manufacturing Discontinuation
ISL8120XIRTZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8121IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8121IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8121IRZ-TR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8121IRZ-TS2568	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8126CRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8126CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8126EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8126IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8126IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8126IRZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re- Design Part Number	Reason
ISL8130IAZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8130IAZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8130IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8130IRZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL8130IRZ-TKR5194	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440AEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440AIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440AIRZ-TS2490	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440AIRZ-TS2718	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440AIRZ-TS2719	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440BEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440BIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440BIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440BIRZ-TR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440CEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9440EVAL2Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
RAA2261104GNP#HA0	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
RTKA226110DE0000BU	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
RTKA226110DE0010BU	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
RTKA226110DE0040BU	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540ACRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540ACRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540ACRZ-TS2490	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540ACRZ-TS2799	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540AIRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540AIRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540AIRZ-TR5453	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540AIRZA	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6540AIRZA-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6539CAZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6539CAZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6539EVAL1	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6539EVAL2	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6539IAZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6539IAZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535CBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535CBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535CRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535CRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535CRZ-TS2378	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535CRZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL6535IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6535IRZ-TK	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-1CR3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-1CR3Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-1CR4Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-1CR4Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-1CR5Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-1CR5Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-2CR3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-2CR3Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-2CR4Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-2CR4Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-2CR5Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292-2CR5Z-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292EVAL2	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6292EVAL2Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6294EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6294IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9301EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9301IRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL9301IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6271ACRZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6271ACRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6271AEVAL1	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL78692-1CR3ZR5503	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re- Design Part Number	Reason
ISL6721AARZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AARZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AARZ-TS2799	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AARZ-TS2800	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AAVZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AAVZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721ABZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AVZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721AVZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6721EVAL3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AABZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AABZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AARZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AARZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AARZ-TS2800	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AAVZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6722AAVZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6726AAZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6726AAZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6726EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6729IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740AIVZA	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740AIVZA-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740AIVZA-TS2800	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740EVAL1	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740EVAL2Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740EVAL3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740IVZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6740IVZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6741IVZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6741IVZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6742AAZA	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6742AAZA-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6742AAZA-TS2800	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6742BAAZA	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6742BAAZA-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6742BEVAL3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6744AABZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6744AABZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6744AAUZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6744AAUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6744AAUZ-TS2705	3/4/2025	12/4/2025	6/4/2026	None	Manufacturing Discontinuation
ISL6744EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745AAUZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745AAUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745AAUZ-TS2712	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745AAUZ-TS2712P6	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745ALEVAL3Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745LEVAL2Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6745UEVAL2Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6752/54EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6752AAZA	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6752AAZA-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6752AAZA-TR5325P6	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6752AAZA-TS2779	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6752DBEVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6753AAZA	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6753AAZA-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6753EVAL1Z	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6840IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6840IRZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6840IUZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6840IUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6842IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6842IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6843IBZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6843IBZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6843IUZ	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation
ISL6843IUZ-T	3/4/2025	9/4/2025	3/4/2026	None	Manufacturing Discontinuation

Page 7 of 7