

Product Change Notification Current Date: 17-Mar-2025

TE Connectivity

Product Change Notification: PCN-22-151722 PCN Date: 12-SEP-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)

D-SUB METAL BACKSHELL

General Description of Changes

Please be aware of an upcoming cosmetic change to the listed part numbers (not affecting the function of the product). Before: After:





Reason for Changes:

Product cosmetic or appearance update

| PCN Attributes: | | | | | |
|----------------------------------|----------------------------|--|--|--|--|
| Product Category: | Kind of Change: | | | | |
| Caps/Covers And Cover Assemblies | Geometry | | | | |
| Change Feature: | Potential Customer Impact: | | | | |
| Label/Marking Change | No Customer Impact | | | | |
| Remarks: | | | | | |
| AMP logo removal from Backshell | | | | | |

| Estimated Dates: | |
|--|--|
| Last Order Date (Obsolete Parts Only): | First Ship Date of Changed Items (Changed Parts Only): |
| | 13-SEP-2022 |
| Last Ship Date of Changed Items (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |
| Effectivity Date: | Date of First Samples: |
| 12-SEP-2022 | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|--------------------|---------------------------------|---------------------|--|---------------------------|------------------------------------|---------------------------|--------------------|
| <u>1-1478762-5</u> | NO | | | | | | No Data Found |
| <u>1-1478763-5</u> | NO | | | | | | No Data Found |
| 1478762-9 | NO | | "EF5285-000", "AMP-0-1478762- 9" | | | | No Data Found |
| <u>1478763-9</u> | NO | | | | | | No Data Found |
| <u>2-1478762-5</u> | NO | | "AMP-2-1478762- 5", "ES4183-000" | | | | No Data Found |
| <u>2-1478763-5</u> | NO | | | | | | No Data Found |
| <u>3-1478762-7</u> | NO | | | | | | No Data Found |
| <u>3-1478763-7</u> | NO | | | | | | No Data Found |
| <u>4-1478763-5</u> | NO | | | | | | No Data Found |
| <u>4-1478763-6</u> | NO | | | | | | No Data Found |
| <u>4-1478763-7</u> | NO | | | | | | No Data Found |
| <u>5-1478762-1</u> | NO | | "CV0348-000", "AMP-5-1478762- 1" | | | | No Data Found |
| <u>5-1478762-2</u> | NO | | | | | | No Data Found |
| <u>5-1478762-3</u> | NO | | | | | | No Data Found |
| <u>5-1478762-4</u> | NO | | | | | | No Data Found |
| <u>5-1478763-1</u> | NO | | | | | | No Data Found |
| <u>5-1478763-2</u> | NO | | | | | | No Data Found |
| <u>5-1478763-3</u> | NO | | | | | | No Data Found |
| <u>5-1478763-4</u> | NO | | | | | | No Data Found |
| <u>5-1478763-7</u> | NO | | | | | | No Data Found |
| <u>6-1478762-6</u> | NO | | | | | | No Data Found |
| 6-1478762-7 | NO | <u>-</u> | | | | | No Data Found |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Number | Affected Revision | Distributed PCN(s) |
|----------------|-------------------|--------------------|
| <u>1478762</u> | N | No Data Found |
| 1478763 | N | No Data Found |